



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

August 16, 2010

Steve Peck
Dominion Homes Inc.
4900 Tuttle Crossing Boulevard
Dublin, OH 43016

**Re: Construction Storm Water Inspection at Baumeister Tract Sections 1 & 2
Franklin County
Permit Number 4GCD00039*AG**

Dear Mr. Peck:

This letter is written in follow-up to a construction storm water inspection conducted by Elizabeth Schaller and Jed Plank of the Ohio EPA at Baumeister Tract in Hilliard, Ohio on August 5, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following issues were noted:

Sediment and Erosion Control:

- The silt fence on the southern portion of the site has failed and will require maintenance at this time.
- Inlet protections must be installed on the north side of the project (see Figure 1).
- Our inspection staff noted mud in the road at both entrances to the project. The entrances/exits must be cleaned to minimize off-site vehicle tracking (See Figure 2).

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,


Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Baumeister Tract, Sections 1 & 2, 8-5-10

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director






Figure 1: Inlet protections must be installed over drains on the northern portion of the project.



Figure 2: Measures must be taken to minimize vehicle tracking.

