



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Central District Office

MAILING ADDRESS:

Caesar Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

P.O. Box 1049
Columbus, OH 43216-1049

July 23, 2010

Jonathan Schlesselman
OSU Chabad House
207 East 15th Street
Columbus, OH 43201

**Re: Construction Storm Water Inspection at Chabad House / Franklin County
Permit Number 4GC02989*AG**

Dear Mr. Schlesselman:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Abigail Tamkin of Ohio EPA at Chabad House located at 6220 Dublin Granville Rd, New Albany, Ohio on July 14, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water permit, the following items were noted;

Sediment and Erosion Control:

- The centralized retention pond lacks proper outlet structure designed for sediment control. Failure to implement effective sediment controls is a direct violation of your General Storm Water Permit. Corrective measure must be taken to install a modified outler structure such as a temporary riser or equivalent within seven days of receipt of this letter, to avoid the potential of escalated action (Figure 1).
- Please establish a proper concrete washout pit in order to minimize contamination threats to waters of the state (Figure 2).

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response to the action items addressed above within ten days from receipt of this letter. A follow up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, CDO/DSW

HK/nsm OSU Chabad House July 14, 2010

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korteski, Director






Figure 1: Outlet structure without proper controls



Figure 2: Improperly constructed concrete washout pit

