



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

September 13, 2011

Scott Ford  
London Industries Inc.  
350 East High Street  
London, OH 43140

**Re: London Industries, Madison County  
Industrial Storm Water Permit 4GR00186\*DG**

Dear Mr. Ford:

This letter is written in regard to the storm water inspection that I conducted at London Industries, located at 350 East High Street, in London, Ohio. The inspection was conducted on September 7, 2011, to determine compliance with your industrial storm water permit. Your facility manufactures plastic molding for the automotive and motorcycle industry. The following items were noted during the inspection:

1. There was construction activity taking place at your facility. There was a 30,000 square foot building addition and a dirt berm being constructed in the rear of the property. The land disturbance was close to an acre. It is requested that if the land disturbance is greater or equal to one acre to apply for a general storm water construction permit. It is also recommended to install silt fence around the earthen berm to prevent sediment from discharging to the storm water drains. It is also recommended to maintain the dandy bag covers on the storm water drain. Please see attached pictures.
2. If you have not already done so, you must modify your industrial storm water permit to update the new name and management of your company.
3. Please be aware that dumpsters should have covers, unless the dumpsters contain only wood or paper.
4. Please send me an electronic copy of your storm water pollution prevention plan (SWP3) and a spill prevention control and countermeasure plan. The plans should be updated annually or when there is a change in management. My e-mail address is [greg.sanders@epa.ohio.gov](mailto:greg.sanders@epa.ohio.gov).
5. Your facility had a covered loading/unloading area. However, there was an excessive amount of oil and grease in the drains in this area. The discharge from the area was being directed to the driveway. Please direct the discharge to a drum. Please see attached picture.

Scott Ford  
London Industries Inc.  
Page -2-

6. There was oil and grease stains on the pavement near a dumpster. Please use better housekeeping measures to prevent staining of the pavement. Please see attached picture.
7. There were drums and totes stored in the rear of your facility. Please be aware that full or partially full containers should be stored in secondary containment under roof. Please be aware that empty containers should be stored upright with a lid. Please see attached pictures.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3851.

Sincerely,




Gregory L. Sanders  
Environmental Specialist  
Division of Surface Water  
Central District Office

c: Jeff Bohne, DSW/CDO


Enclosure

GS/nsm London Industries, September 7, 2011

London Industries  
Install erosion controls  
Stabilize barren areas  
Deer Creek Watershed  
September 7, 2011



London Industries



London Industries  
Store empty, drums upright  
Store partially full, drums  
Deer Creek Watershed  
September 7, 2000  
Photo: [unreadable]

Wild  
Center, Menard, Under roof

