



State of Ohio Environmental Protection Agency

STREET ADDRESS:

Blazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

July 21, 2010

Tony Furguele
Republic Services of Ohio III, LLC
5131 Drinkle Road
Amanda, OH 43102

**Re: Construction Storm Water Inspection at Pine Grove Regional Facility / Fairfield County
Permit Number: 4GC03262*AG**

Dear Mr. Furguele:

This letter is written in follow-up to a construction storm water inspection conducted by Stephen Riley and Elizabeth Schaller of Ohio EPA at Pine Grove Regional Facility in Amanda, Ohio on July 7, 2010. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- The disturbed area on the west side of the existing road which drains into the creek lacks sediment controls (See Figure 1).
- The disturbed area on the east side of the existing road at the top of the hill which drains toward the creek crossing through the property lacks sediment controls.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any questions regarding this letter or my inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.


Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, CDO, DSW

HK/nsm Pine Grove Regional Facility

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director






Figure 1: Lack of sediment controls into creek

