



State of Ohio Environmental Protection Agency

PHYSICAL ADDRESS:

Lazarus Government Center
50 W. Town St., Suite 700
Columbus, Ohio 43215

Central District Office

TELE: (614) 728-3778 FAX: (614) 728-3898
www.epa.state.oh.us

MAILING ADDRESS:

P.O. Box 1049
Columbus, OH 43216-1049

June 30, 2010

Phill Vonderwell
Emerson/Liebert Corporation
1050 Dearborn Drive,
Columbus, OH 43085

**Re: Industrial Storm Water Inspection at Liebert Corporation, Columbus.
Permit Number 4GR00201*DG**

Dear Mr. Vonderwell:

This letter is written regarding the storm water inspection, I conducted at Liebert Corporation in Columbus Ohio on June 2, 2010. The Agency understands this site is currently is covered under the General Storm Water Permit Associated with Industrial Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

Storm Water Pollution Prevention Plan (SWPPP):

- During the inspection, I had the opportunity to briefly evaluate the SWPPP. The major components required under your General Permit have been addressed. I will be evaluating the SWPPP in detail to ensure full compliance with the Storm Water Permit conditions. The plan has been received and is currently subject to review. The SWPPP must be reviewed and updated on a yearly basis to reflect any changes in operations.

Fuelling Island:

- At this time, I am recommending best management practices (BMP's) associated with the storm water runoff for the fuelling island. The BMP's would include but not limited to an elevated fuelling area below a roof associated with the fuel pumps. In addition, considerations for directing the storm water flow to an oil/water separator may be implemented as an alternative.

Scrap Waste Bins:

- During the inspection, I evaluated the scrap waste bins. At this time, I am recommending a cover for this area to minimize exposure to storm water.

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Storm Water Management:

- The majority of operations and exposed materials are located inside the facility. This serves as the optimal BMP to reduce the threat of contaminated storm water discharges from the site. Please continue to utilize this BMP to the maximum extent practical.

Equipment Storage:

- The equipment storage area was evaluated. I did not observe any equipment which poses a significant threat to storm water. Please continue to monitor this area for the potential of storm water contamination. Inspections of this area should be reflected in your self inspection reports.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,



Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office