



4GC0304720110808

2011/08/08

4GC03047

BEDFORD II LANDFILL COVER



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 9, 2011

Steve Geiger
Geiger Excavating Inc.
65 Southwind Drive
Gahanna, OH 43230

**Re: Construction Storm Water Inspection at Bedford II Landfill Cover
Franklin County
Permit Number: 4GC03047*AG**

Dear Mr. Geiger:

This letter is written regarding the storm water inspection I conducted at Bedford II Landfill Cover located at Enterprise Drive in Gahanna, Ohio on July 27, 2011. The Agency understands that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items were noted;

Sediment Pond:

- The temporary skimmer has been compromised. Corrective measures must be conducted to ensure the intended function of the skimmer discharge. The sediment pond will require cleaning as it appears that fifty percent of the capacity of the pond has been eliminated due to accumulated sediments from recent rain events.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at: harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office


Enclosure


c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Geiger Excavating Bedford Landfill

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov





Bedford II Landfill Cover
Big Walnut Watershed
Photo by: Stephen Riley and Lisa Schaller
July 26, 2010

Note: Sediment laden water in pond, lacking
appropriate outlet controls

Figure 1: Sediment laden waters leaving property, skimmer also requires maintenance.

