



4GC0353620110718

2011/07/18

4GC03536

THOMAS WORTHINGTON HIGH SCHOOL



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 19, 2011

Tim Gehring
Worthington City School District
200 East Wilson Bridge Road
Worthington, OH 43085

**Re: Construction Storm Water Inspection at Thomas Worthington High School
Franklin County
Permit Number: 4GC03536*AG**

Dear Mr. Gehring:

This letter is written regarding a storm water inspection conducted by Daelann Farnlacher and Lindsey Boaz of the Ohio EPA at Thomas Worthington High School located at 300 West Dublin-Granville Road Worthington, Ohio on June 28, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- It appears that storm water is currently contained within the current site excavation. Perimeter controls are required once off-site drainage is established.

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Ohio EPA
Division of Surface Water

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm Thomas Worthington High School 6-28-2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov






Figure 1: Silt fence needed along perimeter of site next to Summit



Figure 2: Failed silt fence on north side of site






Figure 3: Failed silt fence at west end of site next to stream

