



4GC0341520110718

2011/07/18

4GC03415

SUPERIOR PLASTICS



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 18, 2011

Ed Grimm
Dublin Building Systems
6233 Avery Rd Box 370
Dublin, OH 43017

**Re: Storm Water Inspection at Superior Plastics / Union County
Permit Number: 4GC03415*AG**

Dear Mr. Grimm:

This letter is written in follow-up to a construction storm water inspection by Kelsey Heyob and Lindsey Boaz of the Ohio EPA, conducted at Superior Plastics located at 8255 Estates Parkway Plain City, Ohio on June 24, 2011. The Agency understands that these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

Sediment and Erosion Controls

- All storm drains should have proper inlet protections installed (See Figure 1).
- A centralized sediment basin was noted and appears to be functioning properly (See Figure 2).
- Silt fencing must be implemented along the contour and control areas where sheet flow is present. The silt fence must be entrenched, otherwise reinstallation will be required (See Figure 3).
- The entrance of the site must be stabilized to minimize off site vehicle tracking (See Figure 4).

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844. In addition, please provide a written response to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

Enclosure

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm Superior Plastics 6-24-2011

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov







Figure 1: Inlet barrier not installed



Figure 2: Centralized Sediment Basin






Figure 3: Perimeter controls should be installed




Figure 4: Minimize off site vehicle tracking

