



\*4GC0343920110711\*

2011/07/11

4GC03439

NET JETS HEADQUARTERS



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 11, 2011

Todd Sloan  
Daimler Group, Inc.  
1533 Lake Shore Drive  
Columbus, OH 43204

**Re: Construction Storm Water Inspection at Net Jets Headquarters  
Franklin County  
Permit Number: 4GC03439\*AG**

Dear Mr. Sloan:

This letter is written regarding a storm water inspection conducted by Harry Kallipolitis, Greg Mann, Lindsay Boaz, Kelsey Heyob, and Daelann Farnlacher of the Ohio EPA at NetJets Headquarters located at 4151 Bridgeway Avenue, Columbus, Ohio 43219 on June 21, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

**Sediment and Erosion Control:**

- Our staff evaluated the centralized sediment basin and noted that a discharge outlet has not been installed. Please ensure that a modified outlet structure is incorporated into the outlet design (See Figure 1).
- Sediment must be removed from the temporary sediment trap located at the west end of the facility. (See figure 2) In addition, the perimeter controls on the west side must be maintained (See Figures 3-4).
- Our team observed barren areas located on the north end of the site. Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days (See Figure 5-6).

Todd Sloan  
Daimler Group, Inc.  
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us). In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,



Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

Enclosures

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO

HK/nsm NetJets Headquarters




Figure 1: Centralized Sediment Pond




Figure 2: Temporary Sediment Trap







Figure 3: Silt Fence on west end of facility



Figure 4: Silt Fence on west end of facility






Figure 5: Barren Land on north end of facility




Figure 6: Barren Land on north end

