



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

May 5, 2010

Certified Mail

Brad Weinischke
Murphy Oil USA, Inc.
200 Peach Street
El Dorado, AR 71730

**RE: Ohio EPA Facility ID 0855100534
Murphy USA #7268 - 1302 East Ash Street, Piqua, OH 45356
Failure to Pass Air to Liquid Ratio Test**

Dear Mr. Weinischke:

WARNING LETTER

On March 25, 2010, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Murphy USA #7268, 1302 East Ash Street in Piqua, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Murphy USA #7268 revealed violations of these regulations.

Murphy USA #7268 did show compliance through the completion of a successful static leak test and dynamic pressure performance test on March 25, 2010, however, this site failed to show compliance with the Air to Liquid ratio (A/L) testing requirements of CARB Executive Order G-70-153-AD on pump #7. Failing to demonstrate compliance with the A/L performance test requirements is a violation of Ohio Administrative Code (OAC) rule and City of Piqua, Ohio Board of Health Air Pollution Control Regulations (CPOBHAPCR) section 3745-21-09 (DDD), OAC rule and CPOBHAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. An Official Order was issued by RAPCA to Murphy USA #7268 on March 25, 2010 to make any needed repairs and reschedule testing within a thirty (30) day time period. To date, no A/L retest has been scheduled with RAPCA at Murphy USA #7268.

Since the above noted GDF is currently operating in violation of OAC rules and CPOBHAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-

Murphy USA #7268

May 5, 2010

Page 2

70-153-AD, it is imperative that Murphy USA #7268 ensure that repairs are made to this site to correct the deficiencies, and reschedule A/L testing to demonstrate compliance.

Murphy USA #7268 shall respond within fourteen (14) days after receipt of this letter. The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,




Brandie K. Lehman

Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	Lisa Holscher	USEPA

COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<p>Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits.</p> <p>1. Article Addressed to:</p> <p>Brad Weinschke Murphy Oil USA, Inc. 700 Peach St El Dorado, AR 71730</p> <p>2. Service Type <input checked="" type="checkbox"/> Certified Mail <input type="checkbox"/> Express Mail <input type="checkbox"/> Registered <input type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> Insured Mail <input type="checkbox"/> C.O.D.</p> <p>3. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>	<p>A. Signature <i>[Signature]</i> <input checked="" type="checkbox"/> Agent <input type="checkbox"/> Addressee</p> <p>B. Received by (Printed Name) _____</p> <p>C. Date of Delivery 5-10-2010</p> <p>D. Is delivery address different from item 1? <input checked="" type="checkbox"/> Yes If YES, enter delivery address below: <input type="checkbox"/> No</p> <p>P.O. Box 7000</p>
<p>2. Article Number (Transfer from service label) 7008 1300 0001 9323 3242</p>	<p>4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>

CONTROL AGENCY
 Piqua, Ohio
 Piqua, Ohio 45422-1280
 Phone: 937-225-3486



**RE: Ohio EPA Facility ID 0855100534
 Murphy USA #7268 - 1302 East Ash Street, Piqua, OH 45356
 Failure to Pass Air to Liquid Ratio Test**

Dear Mr. Weinschke:

WARNING LETTER

On March 25, 2010, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Murphy USA #7268, 1302 East Ash Street in Piqua, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Murphy USA #7268 revealed violations of these regulations.

Murphy USA #7268 did show compliance through the completion of a successful static leak test and dynamic pressure performance test on March 25, 2010, however, this site failed to show compliance with the Air to Liquid ratio (A/L) testing requirements of CARB Executive Order G-70-153-AD on pump #7. Failing to demonstrate compliance with the A/L performance test requirements is a violation of Ohio Administrative Code (OAC) rule and City of Piqua, Ohio Board of Health Air Pollution Control Regulations (CPOBHAPCR) section 3745-21-09 (DDD), OAC rule and CPOBHAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. An Official Order was issued by RAPCA to Murphy USA #7268 on March 25, 2010 to make any needed repairs and reschedule testing within a thirty (30) day time period. To date, no A/L retest has been scheduled with RAPCA at Murphy USA #7268.

Since the above noted GDF is currently operating in violation of OAC rules and CPOBHAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-

