



## REGIONAL AIR POLLUTION CONTROL AGENCY ✓

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-3280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

June 28, 2011

**Certified Mail**

Brad Weinischke

Murphy Oil USA, Inc.

P.O. Box 7000

El Dorado, AR 71731

**RE: Ohio EPA Facility ID 0855100534 - Murphy USA #7268, 1302 E. Ash St., Piqua, OH  
Failure to pass annual stage II vapor recovery compliance testing**

**WARNING LETTER**

Dear Mr. Weinischke:

On May 24, 2011, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Murphy USA #7268, 1302 East Ash Street in Piqua, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at Murphy USA #7268 revealed violations of these regulations.

Pursuant to Ohio Administrative Code (OAC) rule and City of Piqua, Ohio Board of Health Air Pollution Control Regulations (CPOBHAPCR) section 3745-21-09 (DDD)(2) and in accordance with the testing requirements specified in CARB Executive Order G-70-153-AD for Dresser/Wayne WayneVac stage II vapor recovery systems, static leak testing and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. Murphy USA #7268 failed to show compliance with OAC rule and CPOBHAPCR section 3745-21-09 (DDD)(2) and CARB Executive Order G-70-153-AD on May 24, 2011 through the completion of a successful static leak test and A/L test. On this date, A/L testing was not successfully conducted on pumps #5/6, #11/12, and #13/14 and static leak testing failed on the Dresser/Wayne WayneVac stage II vapor control system. An Official Order was issued by RAPCA to Murphy USA #7268 on May 24, 2011 to make any needed repairs and reschedule testing within a thirty (30) day time period. To date, no static leak or A/L retest has been scheduled with RAPCA at Murphy USA #7268.

Murphy USA #7268 (Ohio EPA Facility ID 0855100534)

June 28, 2011

Page 2


Failing to demonstrate compliance with the stage II vapor recovery compliance testing requirements is a violation of OAC rule and CPOBHAPCR section 3745-21-09 (DDD)(2), CARB Executive Order G-70-153-AD, and Ohio Revised Code (ORC) 3704.05.

Since the above noted GDF is currently operating in violation of OAC rule and CPOBHAPCR section 3745-21-09 (DDD)(2), CARB Executive Order G-70-153-AD and ORC 3704.05, it is imperative that Murphy USA #7268 ensure that repairs are made to this site to correct any deficiencies and reschedule testing to demonstrate compliance.

**Murphy USA #7268 shall respond within fourteen (14) days after receipt of this letter.** The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman  
Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	William MacDowell	USEPA, Region V

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Brad Weinischke  
 Murphy Oil USA, Inc.  
 PO Box 7000  
 El Dorado, AR 71731

2. Article Number

(Transfer from service label)

7010 3090 0002 4574 6800

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature

X *[Signature]*

Agent

Addressee

B. Received by (Printed Name)

C. Date of Delivery

7-1-2011

D. Is delivery address different from item 1?  Yes  
 If YES, enter delivery address below:  No

3. Service Type

Certified Mail

Express Mail

Registered

Return Receipt for Merchandise

Insured Mail

C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

**U.S. Postal Service™  
 CERTIFIED MAIL™ RECEIPT  
 (Domestic Mail Only; No Insurance Coverage Provided)**

For delivery information visit our website at [www.usps.com](http://www.usps.com)

**OFFICIAL USE**

7010 3090 0002 4574 6800

Postage \$

Certified Fee

Return Receipt Fee  
 (Endorsement Required)

Restricted Delivery Fee  
 (Endorsement Required)

Postmark  
 Here

To  
 Sir  
 or F  
 City  
 Brad Weinischke  
 Murphy Oil USA, Inc.  
 PO Box 7000  
 El Dorado, AR 71731

PS Form 3800, August 2006

See Reverse for Instructions

