



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

June 30, 2008

Certified Mail

Missy Stanaway
Speedway SuperAmerica LLC
P.O. Box 1500
Springfield, OH 45501

**RE: Ohio EPA Premises No. 0829060320
SSA #5222 – 179 E. Dayton-Yellow Springs Rd., Fairborn, OH 45324
Failure to Pass Annual Stage II Vapor Recovery Compliance Testing**

Dear Ms. Stanaway:

WARNING LETTER

On April 10, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #5222 (SSA #5222) located at 179 E. Dayton-Yellow Springs Road in Fairborn, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #5222 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Greene County Board of Health Air Pollution Control Regulations (GCBHAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #5222 failed to show compliance with OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on April 10, 2008. On this date, an Official Order was issued to SSA #5222 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no additional testing has been scheduled with RAPCA.

Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), OAC rule and GCBHAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05.


SSA #5222
June 30, 2008
Page 2

Since the above noted GDF is currently operating in violation of OAC rules and GCBHAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-70-150-AE, it is imperative that SSA #5222 ensure that repairs are made to this site to correct the deficiencies, and reschedule testing to demonstrate compliance.

SSA #5222 shall respond within fourteen (14) days after receipt of this letter. The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman
Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	Lisa Holscher	USEPA



REGI
Servin

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

MISSY STANAWAY
SPEEDWAY SUPER AMERICA LLC
PO BOX 1500
SPRINGFIELD, OH 45501

COMPLETE THIS SECTION ON DELIVERY

A. Signature

X

B. Received by (Printed Name)

JOHN GARRETT

C. Date of Delivery

JUL 01 2008

D. Is delivery address different from item 1? Yes
If YES, enter delivery address below: No

3. Service Type

- Certified Mail Express Mail
- Registered Return Receipt for Merchandise
- Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number
(Transfer from service label)

7004 1160 0000 6165 4900

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1

Certified Mail

Missy Stanaway
Speedway SuperAmerica
P.O. Box 1500
Springfield, OH 45501

**RE: Ohio EPA Premises No. 0829060320
SSA #5222 - 179 E. Dayton-Yellow Springs Rd., Fairborn, OH 45324
Failure to Pass Annual Stage II Vapor Recovery Compliance Testing**

Dear Ms. Stanaway:

WARNING LETTER

On April 10, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #5222 (SSA #5222) located at 179 E. Dayton-Yellow Springs Road in Fairborn, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #5222 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Greene County Board of Health Air Pollution Control Regulations (GCBHAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #5222 failed to show compliance with OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on April 10, 2008. On this date, an Official Order was issued to SSA #5222 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no additional testing has been scheduled with RAPCA.

Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), OAC rule and GCBHAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05.

