



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

February 12, 2008

Certified Mail

Missy Stanaway

Speedway SuperAmerica LLC

P.O. Box 1500

Springfield, OH 45501

**RE: Ohio EPA Premises No. 0812790443
Speedway SuperAmerica #1015 – 405 S. Burnett Rd., Springfield, OH
Failure to Pass Annual Stage II Vapor Recovery Compliance Testing**

Dear Ms. Stanaway:

WARNING LETTER

On October 4, 2007, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #1015 (SSA #1015) located at 405 South Burnett Road in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #1015 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #1015 failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on October 4, 2007. On this date, an Official Order was issued to SSA #1015 to make any needed repairs and reschedule testing within a thirty (30) day time period. On December 14, 2007, a retest was conducted at SSA #1015, but this GDF failed to show compliance with OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test on this date, as well.

Speedway SuperAmerica LLC #1015
February 12, 2008
Page 2


Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), OAC rule and CCCHDAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05.

Since the above noted GDF is currently operating in violation of OAC rules and CCCHDAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-70-150-AE, it is imperative that SSA #1015 ensure that repairs are made to this site to correct the deficiencies, and reschedule testing to demonstrate compliance.

SSA #1015 shall respond within fourteen (14) days after receipt of this letter. The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman
Air Pollution Control Specialist

cc: Jeff Canan RAPCA
Tom Kalman OEPA
Lisa Holscher USEPA

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

Article Addressed to:

MISSY STANAWAY
 SPEEDWAY SUPERAMERICA LLC
 PO BOX 1500
 SPRINGFIELD, OH 45501

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *Judy Erree* Agent Addressee
 B. Received by (Printed Name)
 C. Date of Delivery
FEB 14

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

Article Number

Transfer from service label)

7004 1160 0000 6165 4443

Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

**RE: Ohio EPA Premises No. 0812790443
 Speedway SuperAmerica #1015 - 405 S. Burnett Rd., Springfield, OH
 Failure to Pass Annual Stage II Vapor Recovery Compliance Testing**

Dear Ms. Stanaway:

WARNING LETTER

On October 4, 2007, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #1015 (SSA #1015) located at 405 South Burnett Road in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #1015 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #1015 failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on October 4, 2007. On this date, an Official Order was issued to SSA #1015 to make any needed repairs and reschedule testing within a thirty (30) day time period. On December 14, 2007, a retest was conducted at SSA #1015, but this GDF failed to show compliance with OAC rule and GCBHAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test on this date, as well.

