



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

September 10, 2008

Certified Mail

Missy Stanaway
Speedway SuperAmerica LLC
P.O. Box 1500
Springfield, OH 45501

**RE: Ohio EPA Facility ID 0812760495
SSA #3369 – 5050 Urbana Road, Springfield, OH 45503
Failure to Pass Annual Stage II Vapor Recovery Compliance Testing**

Dear Ms. Stanaway:

WARNING LETTER

On July 24, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #3369 (SSA #3369) located at 5050 Urbana Road in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #3369 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #3369 failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on July 24, 2008. On this date, an Official Order was issued to SSA #3369 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no additional testing has been scheduled with RAPCA.

Speedway SuperAmerica #3369

September 10, 2008

Page 2


Failing to demonstrate compliance with the testing requirements is a violation of OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), OAC rule and CCCHDAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05.

Since the above noted GDF is currently operating in violation of OAC rules and CCCHDAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-70-150-AE, it is imperative that SSA #3369 ensure that repairs are made to this site to correct the deficiencies, and reschedule testing to demonstrate compliance.

SSA #3369 shall respond within fourteen (14) days after receipt of this letter. The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman

Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	Lisa Holscher	USEPA



REGIO
Serving

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

MISSY STANAWAY
SPEEDWAY SUPERAMERICA LLC
 PO BOX 1500
 SPRINGFIELD, OH 45501

COMPLETE THIS SECTION ON DELIVERY

A. Signature
 X *Jimmy D. Sewell* Agent Addressee

B. Received by (Printed Name)
Jimmy D. Sewell

C. Date of Delivery
SEP 15 2008

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type

Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (Extra Fee) Yes

2. Article Number
(Transfer from service label)

7007 1490 0004 7510 2443

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

Certified Mail

Missy Stanaway
 Speedway SuperAmerica
 P.O. Box 1500
 Springfield, OH 45501

RE: Ohio EPA Facility ID 0812760495
SSA #3369 – 5050 Urbana Road, Springfield, OH 45503
Failure to Pass Annual Stage II Vapor Recovery Compliance Testing

Dear Ms. Stanaway:

WARNING LETTER

On July 24, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) at Speedway SuperAmerica LLC #3369 (SSA #3369) located at 5050 Urbana Road in Springfield, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #3369 revealed violations of state and local air pollution control regulations.

Pursuant to Ohio Administrative Code (OAC) rule and Clark County Combined Health District Air Pollution Control Regulations (CCCHDAPCR) section 3745-21-09 (DDD)(2), and in accordance with the testing requirements specified in CARB Executive Order G-70-150-AE, static leak testing contained in OAC rule 3745-21-10, Appendix A, and air to liquid ratio (A/L) testing shall be successfully conducted at least once in each consecutive twelve-month period. SSA #3369 failed to show compliance with OAC rule and CCCHDAPCR section 3745-21-09 (DDD)(2), through the completion of a successful static leak test and A/L test on July 24, 2008. On this date, an Official Order was issued to SSA #3369 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no additional testing has been scheduled with RAPCA.