



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

January 19, 2007

CERTIFIED MAIL

Mr. Clark Siddle
Alloyd Asbestos Abatement Co.
5700 Webster Street
P.O. Box 13394
Dayton, Ohio 45414

Re: Renovation activities at Standard Register Building #3 and Carroll High School Building

NOTICE OF VIOLATION

Dear Mr. Siddle:

You are hereby notified that the Regional Air Pollution Control Agency (RAPCA) finds Alloyd Asbestos Abatement Co. (Alloyd) to be in violation of local asbestos regulations as they relate to asbestos emission control and waste disposal for asbestos removal operations and proper notification at the above-referenced facilities.

On November 4, 2005, RAPCA received a notification from Alloyd for removal of 134 linear feet and 125 square feet of regulated asbestos-containing material (ACM) in the form of thermal system pipe insulation and 500 square feet of category II nonfriable transit panels from the Standard Register Building #3 located at 600 Albany Street, Dayton, Ohio. The asbestos removal work was scheduled to take place from November 16, 2005 through December 16, 2005. Subsequent revision to the notification changed the completion date to December 1, 2005.

On December 7, 2005, a RAPCA representative performed a routine inspection of the unoccupied above-referenced facility after abatement had been completed on or before December 1, 2005. During this inspection, dry, friable suspect asbestos containing transite material which had been rendered friable during abatement activities was observed throughout the storage building without proper emission control and waste disposal.

Samples were collected and photographs were taken of all the areas in question.

The inspection was conducted for the purpose of determining compliance with the corresponding Montgomery County Hazardous Air Pollution Control Regulation 150 (MCHAPCR 150).

The conditions found during the inspection constitute violations of the MCHAPCRs 153.07 pertaining to proper emission control; and MCHAPCR 153.11 pertaining to waste disposal.



Mr. Clark Siddle
January 19, 2007
Page 2

On July 20, 2005, RAPCA received a notification from Alloyd for removal of 25 linear feet and 200 square feet of regulated asbestos-containing material (ACM) in the form of thermal system insulation from the Carroll High School Building located at 4523 Linden Ave., Dayton, Ohio. The asbestos removal work was scheduled to take place from August 3, 2005 through September 3, 2005.

On August 24, 2005, a RAPCA representative performed a routine inspection of the above-referenced facility. During this inspection a RAPCA representative discovered that asbestos removal operations had been completed prior to the notice date submitted by Alloyd via written notification for asbestos removal from the above-mentioned project. As such, and without a proper update to the notification, RAPCA was unable to perform an inspection of work in progress by Alloyd asbestos removal personnel


The inspection was conducted for the purpose of determining compliance with the corresponding Montgomery County Hazardous Air Pollution Control Regulation 150 (MCHAPCR 150).

The conditions found during the inspection constitute violations of the MCHAPCRs 153.06(D)(2) pertaining to proper notification.

These violations can be resolved through the signing of the enclosed Settlement Agreement which include a civil monetary penalty. This Settlement Agreement supercedes all prior and contemporaneous communications, representations, and agreements, whether oral or written relating to the subject matter herein. Please respond in writing within ten (10) days of receipt of this document

Please contact me or Mr. Bruno Maier at (937)225-4435 if you have any questions or comments or wish to arrange a meeting to discuss this matter further.

Sincerely,



Sarah Gostomsky
Asbestos Coordinator
Monitoring & Analysis Unit

/tlm

Enclosure

7004 1160 0000 6164 9340

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com
OFFICIAL USE

Postage	\$	Postmark Here
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		

Total Pp: Mr. Clark Siddle
 Sent To Alloyd Asbestos Abatement Co.
 Street, Apt or PO Box 5700 Webster Street
 City, State P.O. Box 13394
 Dayton, OH 45414

PS Form 3800, June 2002 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

 Mr. Clark Siddle
 Alloyd Asbestos Abatement Co.
 5700 Webster Street
 P.O. Box 13394
 Dayton, OH 45414

2. Article Number:
(Transfer from service label)

COMPLETE THIS SECTION ON DELIVERY

A. Signature Agent
 X *Mark Woy* Addressee

B. Received by (*Printed Name*) Date of Delivery
1-26-07

D. Is delivery address different from item 1? Yes
 If YES, enter delivery address below: No

3. Service Type
 Certified Mail Express Mail
 Registered Return Receipt for Merchandise
 Insured Mail C.O.D.

4. Restricted Delivery? (*Extra Fee*) Yes

7004 1160 0000 6164 9340