



REGIONAL AIR POLLUTION CONTROL AGENCY

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-3280

937-225-4435 — Fax: 937-225-3486

www.rapca.org

CERTIFIED MAIL

Mr. Tom Wolfe
Alloyd Asbestos Abatement Co.
5734 Webster Street
Dayton, Ohio 45413

8/9/11

**Re: Renovation activities at Dayton Job Corps Building #1 located at 3849 Germantown Pike,
Dayton, Ohio 45418**

NOTICE OF VIOLATION

Dear Mr. Wolfe:

You are hereby notified that the Regional Air Pollution Control Agency (RAPCA) finds Alloyd Asbestos Abatement Co. (Alloyd) to be in violation of federal, state, and local asbestos regulations as they relate to asbestos emission control and disposal of asbestos-containing waste materials at the above-referenced facility.

On June 20, 2007, RAPCA received a notification from Alloyd for the abatement of 1,200 linear feet of regulated asbestos-containing material (ACM) in the form of thermal system insulation from the Dayton Job Corps Building #1 located at 3849 Germantown Pike, Dayton, Ohio. The asbestos removal work was scheduled to take place from July 5 through August 3, 2007. Subsequent revisions extended the completion date to September 5, 2007.

On August 1, 2007, RAPCA performed an inspection, with an Ohio Department of Health representative, at the Dayton Job Corps site. The inspection was performed after abatement was completed by Alloyd. The RAPCA representative observed dry, friable suspect asbestos-containing material (ACM) thermal system insulation (TSI) debris on top of pipe, floors, and horizontal surfaces throughout pipe chases. The RAPCA representative also observed no engineering controls left in-place (i.e., critical barriers/seals in place, no warning signs/demarcation posted) and all Alloyd's equipment removed from the site. Samples were collected and photographs were taken of all areas of concern. The RAPCA representative requested re-cleaning of all areas where abatement activities occurred, thoroughly wetting and properly disposing all ACM and ACM contaminated waste.

The RAPCA inspection was conducted for the purpose of determining compliance with the corresponding Montgomery County Hazardous Air Pollution Control Regulation 150 (MCHAPCR 150), the Ohio Administrative Code (OAC) Asbestos Emission Control Standards and Procedures specified in Chapter 3745-20, and the National Emission Standards for Hazardous Air Pollutants (NESHAP) specified in 40 CFR Part 61, Subpart M.


The conditions found during this inspection constitute violations of the MCHAPCRs 153.07 (D), OAC rule 3745-20-04(A)(1), (A)(6) and 40 CFR Part 61.145 (c)(3), (c)(3)(B), (c)(6) pertaining to asbestos emission controls; MCHAPCRs 153.11(A)(1), OAC rule 3745-20-05(B), and 40 CFR Part 61.150(a) pertaining to disposal of asbestos-containing waste materials.

Mr. Tom Wolfe
August 8, 2011
Page 2

These violations are considered resolved through this Notice of Violations (NOV). Please be advised that violations of this nature may carry substantial civil penalties at the federal, state and/or local level.

Please contact me or Mr. Andrew Roth at (937) 225-4435 if you have any questions or wish to schedule a meeting to discuss this matter further.

Sincerely,

A handwritten signature in cursive script that reads "Sarah Gostomsky". The signature is written in black ink and is positioned above the typed name.

Sarah Gostomsky
Asbestos Coordinator
Monitoring & Analysis Unit

U.S. Postal Service™
CERTIFIED MAIL™ RECEIPT
(Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

7010 3090 0002 4574 5261

Postage	\$	
Certified Fee		
Return Receipt Fee (Endorsement Required)		
Restricted Delivery Fee (Endorsement Required)		
Total	Mr. Tom Wolfe	
Sent To	Alloyd Asbestos Abatement Co.	
Street, or PO	5734 Webster Street	
City, S	Dayton, Ohio 45413	

PS Form 3800, August 2006 See Reverse for Instructions

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Mr. Tom Wolfe
 Alloyd Asbestos Abatement Co.
 5734 Webster Street
 Dayton, Ohio 45413

2. Article Number
 (Transfer from service label)

7010 3090 0002 4574 5261

COMPLETE THIS SECTION ON DELIVERY

A. Signature		<input type="checkbox"/> Agent
<input checked="" type="checkbox"/>		<input type="checkbox"/> Addressee
B. Received by (Printed Name)	C. Date of Delivery	
D. Is delivery address different from item 1? <input type="checkbox"/> Yes		
If YES, enter delivery address below: <input type="checkbox"/> No		
3. Service Type		
<input type="checkbox"/> Certified Mail	<input type="checkbox"/> Express Mail	
<input type="checkbox"/> Registered	<input type="checkbox"/> Return Receipt for Merchandise	
<input type="checkbox"/> Insured Mail	<input type="checkbox"/> C.O.D.	
4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes		