



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

June 8, 2009

RE: RTI ALLOYS MPD
3GR00804*DG
STARK COUNTY

Mrs. Kathleen Nevitt
Environmental, Health & Safety Coordinator
RTI Alloys
208 15th St SW
Canton, Ohio 44707

Dear Mrs. Nevitt:

This office has reviewed the SWPPP submitted on May 22, 2009. The following items must be adequately addressed:

- 1) The plan should contain specific storm water annual training dates and verification that the training was conducted.
- 2) Determine where the storm water exits your property and label this outfall-001 on your site map.
- 3) Include on your site map the location of the pipes, direction of flow, inlets / catch basins, and outfalls of storm sewers.
- 4) The map provided with your SWPPP lacks details (topography, location of outfalls, location of sanitary and storm water lines under property); please provides at least 11 X 17 inch drawings for legibility.
- 5) Conduct a thorough site inspection for non-storm water discharges (noticed a flow in storm sewer on Cleveland Avenue from this property during inspection on June 3, 2009).

Please resubmit the updated SWPPP with the above listed items adequately addressed within 30 days of the receipt of this letter as required by the General permit. If you should have any questions concerning this letter, feel free to contact this writer at (330) 963-1128.

Sincerely,

David Rischar
Assistant to the District Engineer
Division of Surface Water

DR/mt

