



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

July 6, 2009

RE: MAHONING COUNTY
CITY OF YOUNGSTOWN
WILLIAMSON COLLEGE OF BUSINESS

NOTICE OF DEFICIENCIES

Mr. Richard E. Feldmiller
Youngstown State University
1 University Plaza
Youngstown, OH 44555

Dear Mr. Feldmiller:

On July 1, 2009, this office performed a compliance inspection of storm water best management practices (BMPs) at the above referenced site. While on site I spoke with Rick Carrera. Our records indicate that this site is covered by an Ohio EPA General Storm Water Permit for Construction Activities #3GC04339*AG

Our inspection revealed that the storm water BMPs for this site are already in place. However, the following items should be addressed:

- The silt fencing adjacent to Rayan and near the construction entrance is not trenched and will let sediment laden runoff get off site. This silt fence must be trenched or re-installed.
- The exposed storm sewer must be protected. Inlet protection must be installed; a filter sock is not sufficient in keeping sediment from entering the storm drain.

Please provide this office with a letter of response indicating the corrective action you will take to address these deficiencies, within 7 days of receipt of this letter. All corrective actions should be completed by July 20, 2009.

If you have any questions, please contact me at (330) 963-1138 or e-mail me at marcus.hollenbank@epa.state.oh.us. Thank you for your prompt attention to these matters.

Sincerely,

Marcus Hollenbank
Assistant to the District Engineer
Division of Surface Water

MH/mt

cc: Rick Carrera, Marous Brothers Construction
Engineer, City of Youngstown