

**Environmental  
Protection Agency**

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Kordecki, Director

August 9, 2010

RE: SUMMIT COUNTY  
SUMMIT LAKE BASIN  
CITY OF AKRON  
DR THOMAS MC EBRIGHT  
COMMUNITY LEARNING CENTER

**NOTICE OF DEFICIENCY**

Mr. Brian Ward  
70 N. Broadway Avenue  
Akron, OH 44308

Dear Mr. Ward:

On August 3, 2010, Ohio EPA conducted a follow-up inspection of the Dr. Thomas Mc Ebright Community Learning Center project, located at 349 Cole Avenue, City of Akron, Summit County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04519\*AG. I was accompanied by Lindsey Olmstead of Ohio EPA. The inspection documented the following:

- The sediment trap has been eliminated (Figure 1). Issues with the sediment trap were documented during the first inspection and discussed with the contractor and engineer. The underground detention system is now being used. The underground detention system must be maintained and cleaned out as necessary.
- Improper inlet protection has been installed in the site's storm sewer inlets (Figures 2 and 3). A conversation between the site's engineer, Paul Schmoll, and myself allowed for the use of filter fabric wrapped around the grates with stone being placed on top of the grates. It was observed during the inspection that this method is not being utilized on all storm sewer inlets. **Install an approved method of inlet protection on all of the site's storm sewer inlets immediately.**
- Offsite tracking of sediment was observed (Figure 4). Mud spilled, dropped, washed or tracked onto public roads shall be removed immediately by scraping or sweeping.


Mr. Brian Ward  
Dr. Thomas Mc Ebright Community Learning Center  
August 9, 2010  
Page 2

- At the time of inspection it was noted that the site work contractor, Mr. Excavator, had not filed a co-permittee notice of intent (NOI). The forms and instructions can be obtained from:

<http://www.epa.state.oh.us/dsw/storm/stormform.aspx>

A written report detailing how the above deficiencies will be addressed must be submitted to Ohio EPA within seven days of receiving this letter. The above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1128.

Sincerely,



Sean Green  
Assistant to the District Engineer  
Division of Surface Water

SG/mt

cc: Ilario Simonetta, RPJ Construction Managers  
Joan Hug-Anderson, Summit SWCD




Figure 1. The sediment trap has been eliminated and final grading is taking place.



Figure 2. Improper inlet protection was observed.




Figure 3. Improper inlet protection was observed.



Figure 4. Offsite tracking of sediment was observed.