



**Environmental  
Protection Agency**

Ted Strickland, Governor  
Lee Fisher, Lt. Governor  
Chris Korleski, Director

July 19, 2010

RE: TRUMBULL COUNTY  
MILL CREEK BASIN  
JOHNSTON/ VERNON TOWNSHIPS  
SR 88 BETWEEN SR 5 AND SR 7 (PID #77865)

Ms. Ann Powell  
2088 S. Arlington Road  
Akron, OH 44306

Dear Ms. Powell:

On July 15, 2010, Ohio EPA conducted an inspection of the State Route 88 project located between State Route 5 and State Route 7, Johnston and Vernon Townships, Trumbull County (site). Ohio EPA records indicate that the site is covered by the General National Pollutant Discharge Elimination System (NPDES) Permit for Storm Water Associated with Construction Activity (General Storm Water Permit), permit No. 3GC04709\*AG. The inspection documented the following:

- At the time of inspection, crews were working within the immediate vicinity of the newly installed culvert. Gery Patman of ODOT stated that she expects earth-disturbing activities near the culvert and stream to be completed by the end of the month of July.
  1. For all areas within 50 feet of a surface water of the State: Temporarily stabilize within 2 days, any areas that will remain idle for 21 days or longer. Permanently stabilize within 2 days, any areas that are at final grade.
  2. For all other areas: Temporarily stabilize within 7 days, any areas that will remain idle for 21 days or longer. Permanently stabilize within 7 days, any areas that are at final grade.

Any above deficiencies must be addressed within 14 days of receiving this letter. Should you have any questions regarding this matter, please contact me at your earliest convenience by phone at (330) 963-1128, or by email at [Sean.Green@epa.state.oh.us](mailto:Sean.Green@epa.state.oh.us)

Sincerely,

Sean Green  
Assistant to the District Engineer  
Division of Surface Water

SG/mt

cc: Shelly and Sands, Inc.



Figure 1. Earth disturbing activities were taking place along the stream banks at the time of inspection.



Figure 2. Earth disturbing activities were taking place along the stream banks at the time of inspection.