



State of Ohio Environmental Protection Agency

Northwest District Office

347 North Dunbridge Road
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Re: Hancock County
Ohio Orthopaedic and Sports Medicine
Construction
Storm Water

July 28, 2009

Ohio Orthopaedic and Sports Medicine
Mr. Stan Phillips
301 West Wallace Street
Findlay, Ohio 45840

And

Clouse Construction Corporation
Mr. Jerry Kirian
4382 W. Township Road 90
New Riegel, Ohio 44853

And

R.D. Jones Excavating Inc.
Mr. Tom McClellan
PO Box 127
Harrod, OH 45850

Dear Mr. Phillips, Mr. Kirian and Mr. McClellan:

On July 9, 2009, I inspected Ohio Orthopaedic and Sports Medicine at 1950 Fostoria Avenue, in Findlay. The purpose of my visit was to ensure that the violations noted in my June 22, 2009 letter had been corrected. The site operates under the National Pollutant Discharge Elimination System (NPDES) permit for storm water discharges associated with construction activity (Construction General Permit), Facility ID No. 2GC02200. Mr. Jerry Kirian, Clouse Construction, was present to provide information on the project.

I received Mr. Bruce Shook's letter dated June 29, 2009, describing what corrective actions have been taken to address items noted during Ohio EPA's May 27, 2009, inspection of Ohio Orthopaedic and Sports Medicine

As a result of the inspection, I have the following comments:


1. A line was attached to the Delaware skimmer outlet in the sediment settling pond to stabilize it as well as allow for it to be pulled to the banks.
2. Inlet protection had been installed on the catch basin located along Bright Road. Filter fabric was supported by a 2 x 4 frame and was entrenched.

Mr. Stan Phillips
Mr. Jerry Kirian
Mr. Tom McClellan
July 28, 2009
Page Two

3. The soil stockpile on the north side of the property had been seeded. An open face remained on the west side of the stockpile.
4. The banks of both ponds had been regraded and seeded. I observed some grass growth.
5. According to Mr. Kirian the pond at the center of the property was currently being trenched to install a lighting system within the pond.

Your reply appears acceptable and we appreciate your cooperation in this matter. If there are any questions, please contact me at (419) 373-3006.

Sincerely,



Danielle Meienburg
Division of Surface Water
Storm Water Program

/lb

pc

~~MWDOT file~~

Brian Hurt P.E., Findlay City Engineer
Randy Greeno, Findlay Water Pollution Control Center