



## **REGIONAL AIR POLLUTION CONTROL AGENCY**

Serving Clark, Darke, Greene, Miami, Montgomery & Preble Counties

117 South Main Street, Dayton, Ohio 45422-1280

937-225-4435 — Fax: 937-225-3486

[www.rapca.org](http://www.rapca.org)

September 11, 2008

### **Certified Mail**

Missy Stanaway  
Speedway SuperAmerica LLC  
P.O. Box 1500  
Springfield, OH 45504

**RE: Ohio EPA Facility ID 0855010466  
SSA #6348 – 120 N. Miami Ave, Bradford, OH 45308  
Failure to Pass Air to Liquid Ratio Test**

Dear Ms. Stanaway:

### **WARNING LETTER**

On July 31, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Speedway SuperAmerica LLC #6348 (SSA #6348) located at 120 North Miami Avenue in Bradford, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #6348 revealed violations of state and local air pollution control regulations.

SSA #6348 did show compliance through the completion of a successful static leak test on July 31, 2008, however, this site failed to show compliance with the Air to Liquid ratio (A/L) testing requirements of CARB Executive Order G-70-164-AA on pumps #1, #2, and #3. Failing to demonstrate compliance with the A/L performance test requirements is a violation of Ohio Administrative Code (OAC) rule and Miami County Board of Health Local Air Pollution Control Regulations (MCBHLAPCR) section 3745-21-09 (DDD), OAC rule and MCBHLAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. On July 31, 2008, an Official Order was issued to SSA #6348 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no A/L retest has been scheduled with RAPCA.

Since the above noted GDF is currently operating in violation of OAC rules and MCBHLAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-


Speedway SuperAmerica LLC #6348  
September 11, 2008  
Page 2

70-164-AA, it is imperative that SSA #6348 ensure that repairs are made to this site to correct the deficiencies, and reschedule A/L testing to demonstrate compliance.

**SSA #6348 shall respond within fourteen (14) days after receipt of this letter.** The response shall include the intended retest date for this GDF. Your tester should contact Lynn Thompson at (937) 225-4437, to ensure a RAPCA representative is present at your scheduled testing.

Failure to perform the required testing will subject this facility to further enforcement actions, which may include penalties. If you have any questions or comments concerning this matter, please feel free to contact me at (937) 225-5923.

Sincerely,



Brandie K. Lehman  
Air Pollution Control Specialist

cc:	Jeff Canan	RAPCA
	Tom Kalman	OEPA
	Lisa Holscher	USEPA

**SENDER: COMPLETE THIS SECTION****COMPLETE THIS SECTION ON DELIVERY**

- 1 Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- 2 Print your name and address on the reverse so that we can return the card to you.
- 3 Attach this card to the back of the mailpiece, or on the front if space permits.

A. Signature  
 Agent  
 Addressee  
*J. P. Sewell*

B. Received by (Printed Name)  
*Jimmy P Sewell*

C. Date of Delivery  
*SEP 12 2008*

D. Is delivery address different from item 1?  Yes  
 If YES, enter delivery address below:  No

**CONTROL AGENCY**

omy & Preble Counties  
 io 45422-1280  
 225-3486

Article Addressed to:  
 Missy Stanway  
 Speedway SuperAmerica LLC  
 PO Box 1500  
 Springfield, OH 45504

3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

2. Article Number  
 (Transfer from service label) 7007 1490 0004 7509 8104

PS Form 3811, February 2004 Domestic Return Receipt 102595-02-M-1540

**RE: Ohio EPA Facility ID 0855010466  
 SSA #6348 – 120 N. Miami Ave, Bradford, OH 45308  
 Failure to Pass Air to Liquid Ratio Test**

Dear Ms. Stanaway:

**WARNING LETTER**

On July 31, 2008, the Regional Air Pollution Control Agency (RAPCA) conducted an inspection and witnessed a performance test of the gasoline dispensing facility (GDF) located at Speedway SuperAmerica LLC #6348 (SSA #6348) located at 120 North Miami Avenue in Bradford, Ohio. The purpose of this inspection and performance test was to determine the GDF's compliance status with applicable state and local air pollution control regulations. This inspection/test at SSA #6348 revealed violations of state and local air pollution control regulations.

SSA #6348 did show compliance through the completion of a successful static leak test on July 31, 2008, however, this site failed to show compliance with the Air to Liquid ratio (A/L) testing requirements of CARB Executive Order G-70-164-AA on pumps #1, #2, and #3. Failing to demonstrate compliance with the A/L performance test requirements is a violation of Ohio Administrative Code (OAC) rule and Miami County Board of Health Local Air Pollution Control Regulations (MCBHLAPCR) section 3745-21-09 (DDD), OAC rule and MCBHLAPCR section 3745-15-04, and Ohio Revised Code (ORC) section 3704.05. On July 31, 2008, an Official Order was issued to SSA #6348 to make any needed repairs and reschedule testing within a thirty (30) day time period. To this date, no A/L retest has been scheduled with RAPCA.

Since the above noted GDF is currently operating in violation of OAC rules and MCBHLAPCR sections 3745-21-09 (DDD) and 3745-15-04, and CARB Executive Order G-