



State of Ohio Environmental Protection Agency

Northwest District Office

347 North Dunbridge Road
Bowling Green, OH 43402-9398

TELE: (419) 352-8461 FAX: (419) 352-8468
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

Re: Hancock County
Oak Mallett Golf Course
PWS ID# 3233112
STU ID# 3269801


February 21, 2008

Mr. Mike Mallett, President
Universal Golf
921 South Main Street
Findlay, Ohio 45840

OH3233112

OAK MALLETT GOLF COURSE

2/21/2008



Dear Mr. Mallett:

Subject: NOV for Failure to Respond to Significant Deficiencies

This letter is notification that the Oak Mallett Golf Course is in violation of the Ohio Administrative Code (OAC) Rule 3745-81-60(D) for failure to respond in writing within 45 days indicating how and on what schedule the system will address the requirements listed in my correspondence dated January 3, 2008. The last survey of the Oak Mallett Golf Course's water system was performed on December 11, 2007, and the following was identified as a corrective action needing to be addressed:

1. Provide an air gap for the drain lines of the ion-exchange water system. [OAC Rule 3745-95-02(A)]

The water system must respond in writing within 15 days from the date of this letter with the required information. Failure to comply may result in further enforcement action.

If you have any questions regarding this letter or any other matter involving your water system, please feel free to contact me at (419)373-3089 or via email at jill.schiefer@epa.state.oh.us.

Sincerely,

Jill A. Schiefer
Environmental Specialist II
Division of Drinking and Ground Waters

/cs

pc: Dave Evans, DDAGW, OFAS, CO
Hancock County Health Department
Ty Trefl, Operator
~~DDAGW, NWDO File~~

ec: Linda Benham, DDAGW, NWDO File
NWDO Follow-up File