




**Environmental
Protection Agency**

Ted Strickland, Governor
Lee Fisher, Lt. Governor
Chris Kortaski, Director

OH6237212

CHARLES JONES PRODUCE LLC

12/14/2010



Re: Ottawa County
Charles Jones Harris-Salem AMLC
TNC PWS
PWS ID# OH6237212
STU ID# 6256966

December 14, 2010

Certified Mail 7009 1680 0002 4297 3626

Mr. Charles Jones
Charles Jones Produce
P. O. Box 45
Oak Harbor, Ohio 43449

Dear Mr. Jones:

Subject: Notice of Violation for Failure to Respond to a Significant Deficiency

This letter is notification that the Charles Jones Harris-Salem AMLC has not complied with requirements issued during this Agency's last survey performed on September 29, 2010, in violation of rule 3745-81-60 of the Ohio Administrative Code (OAC). The AMLC was notified in correspondence dated October 20, 2010, to respond in writing no later than 45 days, with time frames for:

1. A Siting Plan for Total Coliform monitoring was not on file. Prepare a Total Coliform Sample Siting Plan for Total Coliform as required by OAC Rule 3745-81-21. A plan was started with Mr. Hurst during the survey. This plan should be completed, updated as necessary, and remain on file.
2. OAC Rule 3745-9-04(A)(6) states, "Potential sources of contamination shall not be constructed or placed within the sanitary isolation radius of a public water system well." Dumpsters for the facility are located within the required 70' isolation distance for this well and must be moved.
3. OAC Rule 3745-9-05(O) states, "Well casing height above finished grade shall be at least twelve inches..." In addition, OAC Rule 3745-9-05(O)(2) states, "The finished grade shall be sloped for surface water runoff away from the well." The finished grade around the well must be sloped away from the well in accordance with OAC Rule 3745-9-05(O)(2) and the well casing height must be twelve inches above finished grade. The well casing must be "structurally sound, watertight throughout its length, and have threaded and coupled, or welded joints." The joint at approximately 4" above grade is not connected and the well casing is dented and rusted. The well casing will need to be cut to remove the dented and rusted portion and an additional section of casing will need to be properly attached to meet the height requirements.

Mr. Charles Jones
December 14, 2010
Page Two

4. OAC Rule 3745-9-05(P) states "A well shall have a well cap or seal to prevent the entrance of water, dirt, animals, insects, or other foreign matter. The top of the casing at its finished height shall be cut so that the surface will fit flush with the well cap and provide a tight seal. The well cap or seal shall fit securely to the top of the well casing, be secured with screws or other appropriate connections, and vent to the atmosphere ... Electrical conduit connections on the well cap or seal shall be threaded and sealed to prevent the entrance of insects and water." The well does not have the appropriate conduit seal on the cap. Install a cap on that includes a conduit connection that meets OAC Rule 3745-0-05(P).
5. OAC Rule 3745-9-05(T) states "A vent shall be provided on all well caps and seals ... A well vent shall be self-draining, screened with a non-corroding mesh screen of fifteen to thirty mesh, pointed downward at or above the top of the casing or pitless unit. A vent shall terminate not less than twelve inches above ground surface." The well does not have an appropriate vent on the cap. Install a cap with a vent that meets the specifications identified in OAC 3745-9-05(T).
6. OAC Rule 3745-95-04(A) states "An approved backflow prevention device shall be installed on each service line to a consumer's water system serving premises, where in the judgment of the supplier of water or the director, a pollutional, system, health or severe health hazard to the public water system exists." Ensure that an approved backflow prevention device is installed on each service line where a pollutional, system, health or severe health hazard to the public water system exists. Such a device should be installed on the external hose bibb or a new bibb should be installed with an integrated vacuum breaker.

The water system must respond in writing within 15 days from the date of this letter with the required information. Failure to comply may result in further enforcement action.

If you have any questions regarding this letter, or any other matter involving your water system, contact me at 419-373-3101.

Sincerely,



Chris Riddle
Environmental Specialist 2
Division of Drinking and Ground Waters

/cs

pc: Don Hurst
Gene Phillips, Ohio Department of Health
Central Office, DDAGW
~~DDAGW, NWDO File~~

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<ul style="list-style-type: none"> Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. Print your name and address on the reverse so that we can return the card to you. Attach this card to the back of the mailpiece, or on the front if space permits. 	<p>A. Signature <input checked="" type="checkbox"/> Agent <input checked="" type="checkbox"/> Addressee</p> <p>B. Received by (Printed Name) <input type="checkbox"/> C. Date of Delivery</p>
<p>1. Article Addressed to:</p> <p>Mr. Charles Joe Harris - Salem PO Box 45 Oak Harbor, Ohio 43449</p>	<p>D. Is delivery address different from item 1? <input type="checkbox"/> Yes <input type="checkbox"/> No If YES, enter delivery address below:</p> <p style="text-align: center; color: red; font-weight: bold;">DEC 22 2010</p> <p>3. Service Type <u>USPS</u></p> <p><input checked="" type="checkbox"/> Certified Mail <input type="checkbox"/> Express Mail <input type="checkbox"/> Registered <input type="checkbox"/> Return Receipt for Merchandise <input type="checkbox"/> Insured Mail <input type="checkbox"/> C.O.D.</p> <p>4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>
<p>2. 7009 1680 0002 4297 3626</p>	<p style="text-align: right;"><i>Spolu/CA</i></p>
<p>PS Form 3811, February 2004</p>	<p style="text-align: center;">Domestic Return Receipt</p> <p style="text-align: right;">102596-02-M-1540</p>

U.S. Postal Service TM *Spolu/CA*
CERTIFIED MAIL TM RECEIPT
 (Domestic Mail Only; No Insurance Coverage Provided)

For delivery information visit our website at www.usps.com

OFFICIAL USE

Postage	\$.44	<div style="text-align: right; color: red; font-weight: bold;">Ohio EPA</div> <div style="text-align: center;">  </div>
Certified Fee			
Return Receipt Fee (Endorsement Required)			
Restricted Delivery Fee (Endorsement Required)			
Total Postage & Fees	\$	5.54	

Sent to Charles Joe Harris - Salem *Amto*
 Street, Apt. No., or PO Box No. PO Box 45
 City, State, ZIP+4 Oak Harbor, Ohio 43449

PS Form 3806, August 2006 See Reverse for Instructions

7009 1680 0002 4297 3626