

**Environmental  
Protection Agency**

Ohio Department of Public Safety  
Governor  
Lt. Governor  
Director

November 4, 2011

RE: AMERICAN LANDFILL  
3IN00169  
STARK COUNTY

Mr. Mohammed Ali  
Engineering Manager  
American Landfill Inc.  
7916 Chapel Street, SE  
Waynesburg, Ohio 44688

Dear Mr. Ali:

On November 1, 2011, this writer conducted a compliance evaluation inspection of your facility. You represented American Landfill during the inspection.

All the sediment ponds appeared to be in good condition. There were no visual problems with any of the outfalls. The under drain treatment system was found to be in good operation and maintenance condition.

A review of your Discharge Monitoring Reports (DMRs) covering the period January 2010 through October 2011 revealed the following effluent violations:

Reporting Period	Station	Parameter	Limit Type	Limit	Reported Value	Violation Date
February 2011	006	Total Suspended Solids	1D Conc	45	58	2/17/2011
February 2011	006	Total Suspended Solids	30D Conc	30	58	2/1/2011
November 2010	004	pH	1D Conc	9.0	9.4	11/8/2010
May 2011	001	Total Suspended Solids	1D Conc	45	67	5/25/2011
May 2011	001	Total Suspended Solids	30D Conc	30	67	5/1/2011
May 2011	002	Total Suspended Solids	30D Conc	30	43	5/1/2011
July 2011	001	Total Suspended Solids	1D Conc	45	48	7/21/2011
July 2011	001	Total Suspended Solids	30D Conc	30	48	7/1/2011

If you should have any questions concerning any of the above, feel free to contact this writer at (330) 963-1255.

Sincerely,



Todd Surrena  
Engineering Geologist  
Division of Surface Water

TMS/cs

File: Industrial Permit/Compliance