



State of Ohio Environmental Protection Agency

Southeast District Office

2195 Front Street
Logan, Ohio 43138

TELE: (740) 385-8501 FAX: (740) 385-6490
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 25, 2008

Re: Muskingum County
Dillon State Park WWTP
CEI 2009
OPP00021*AD; OH0037478
Correspondence (PWW)

Mr. Chuck Ainsco, Class III Operator
Dillon State Park WWTP
5265 Dillon Hills Drive
Nashport, Ohio 43830

Dear Mr. Ainsco:

On July 31, 2008, I conducted a compliance evaluation inspection at the Dillon State Park wastewater treatment facilities. I inspected the #1 Service Center plant and the #2 Beach Campground plant. The Sportsman's Park facility is no longer in operation and is being utilized as a holding tank and has been approved for use by the Ohio EPA. The waste from the Sportsman's park is being disposed of at the #1 Service center plant. I was accompanied by Phil Webb and Joe May, Interns, Ohio EPA; Greg Masterson, Treatment Plant Operations Manager, ODNR; Jake Twyman, OIT, ODNR and you. The following are comments from the inspection:

- **The Ultrasonic Flow Meter is past due for calibration**
- **There is a problem with red worms in the aeration basin**

The Ultrasonic Flow Meter is past due for calibration:

The flow meter had not been calibrated for a few years and should be calibrated at least yearly. Regular maintenance should be provided to all equipment in the plant. You should consult the manufacturers specifications for calibration frequencies. Without proper calibration, this could lead to erroneous readings being reported on your monthly DMR.


There is a problem with red worms in the aeration basin:

This problem was brought to my attention and after consulting with Keith Kroeger of the Ohio EPA's assistance group determined this condition was caused possibly by the plant being underfed and too much air in the basin. I suggested to Mr. Ainsco to call Mr. Kroeger about further solutions to this problem.

Please respond to this letter within 30 days of receipt. An inspection report is attached.

If you have any questions or additional comments, please feel free to call at (740) 380-5227.

Sincerely,



Scott Foster
Environmental Specialist 2
Division of Surface Water

SF/dh

Enclosure

- c: Tara Lee, ODNR
- c: Greg Masterson, ODNR
- c: Mark West, Regional Manager, Dillon State Park

NPDES
Compliance Inspection Report

A. NATIONAL DATA SYSTEM CODING

Permit No.	NPDES No.	Date	Inspection Type	Inspector	Facility Type
OPP00021*AD	OH0037478	July 31, 2008	C	S	1

B. FACILITY DATA

Name and Location of Facility Inspected	Entry Time	Permit Effective Date
Dillon State Park WWTP 5265 Dillon Hills Drive Nashport, Ohio 43830	10:15 AM	March 1, 2007
	Exit Time	Permit Expiration Date
	10:50 AM	February 29, 2012

Name(s) and Title(s) of On-Site Representative(s)	Phone Number(s)
Chuck Ainsco, Class III Operator	740-891-1837
Name, Address and Title of Responsible Official	Phone Number
Mark West, Regional Manager 5265 Dillon Hills Drive Nashport, Ohio 43830	740-452-4377


C. AREAS EVALUATED DURING INSPECTION

<u>S</u> Permit	<u>M</u> Flow Measurement	<u>N</u> Pretreatment
<u>S</u> Records/Reports	<u>S</u> Laboratory	<u>S</u> Compliance Schedules
<u>S</u> Operations & Maintenance	<u>S</u> Effluent/Receiving Waters	<u>S</u> Self-Monitoring Program
<u>S</u> Facility Site Review	<u>S</u> Sludge Storage/Disposal	<u>N</u> Other
<u>N</u> Collection System		

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

D. SUMMARY OF FINDINGS/COMMENTS (attach additional sheets if necessary)


See Attached Letter.



Scott Foster, Inspector, Ohio EPA, Southeast District Office

8/25/08

Date



Timothy M. Campbell, Reviewer, Ohio EPA, Southeast District Office

8/25/08

Date