



State of Ohio Environment



Northeast District

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

August 12, 2008

RE: CARROLL COUNTY
MOHAWK UTILITIES, INC.
COMMUNITY WATER SYSTEM
PWS ID # OH1000812
STU ID. NO. 1053071 (Plant No. 2)

Mr. Jon Robertson, Superintendent
Mohawk Utilities, Inc.
7326 Canton Road, NW
P.O. Box 566
Malvern, Ohio 44644

NOTICE OF VIOLATION

Dear Mr. Robertson:

This office has reviewed the monthly operating reports for June 2008. The results indicate that on one occasion, an exceedance of the secondary Maximum Contaminant Level (MCL) for iron occurred at STU ID No. 1053071 (Plant No. 2). This exceedance included:

<u>Date</u>	<u>Contaminant</u>	<u>Level (milligrams/Liter) (mg/L)</u>
June 17, 2008	Iron	0.397

The Ohio Administrative Code (OAC) Rule 3745-82-02 has set the secondary MCL for iron at 0.3 mg/L. Be advised that the listed result is above the secondary MCL for iron. This office is requesting you provide an explanation of why the exceedance occurred. Submit your response to this office within 30 days of the date of this letter.

Sincerely,

Cynthia M. Petretich
Environmental Specialist
Division of Drinking and Ground Waters

CMP/ams

cc: Dave Evans, Ohio EPA, Central Office, DDAGW
Kim Eters, Ohio EPA, NEDO, DDAGW

ec: Stivo DiFranco, Supervisor, Ohio EPA, NEDO, DDAGW