



**Environmental  
Protection Agency**

**John R. Kasich, Governor**  
**Mary Taylor, Lt. Governor**  
**Scott J. Nally, Director**

January 18, 2012

RE: Trumbull County  
Metalico Youngstown, Inc.  
NPDES Permit No. OHR000004  
Ohio EPA Permit No. 3GR00374\*DG  
Industrial Storm Water Inspection

Glenda Brooks, QES Administrator  
Metalico Youngstown, Inc.  
1420 Burton Street SE  
Warren, OH 44484

Dear Ms. Brooks:

On January 4, 2012, Ohio EPA conducted an inspection at Metalico Youngstown, Inc. - Warren Facility, located at 1420 Burton Street SE, City of Warren, Trumbull County (facility). During the inspection, Ohio EPA was represented by Tomas Parry and the undersigned. The facility was represented by you, Lance Grimes, General Manager, and Ben Sunderlin, Operations Manager.

According to Ohio EPA's records, the facility's industrial activities are categorized by Standard Industrial Classification (SIC) Code 5093, Scrap and Waste Materials, and is authorized by General National Pollutant Discharge Elimination System Permit for Storm Water Associated with Industrial Activity (General Storm Water Permit), permit No. 3GR00374\*DG.

**Site Inspection**

The inspection documented the following deficiencies occurring at the facility that must be addressed via appropriate best management practices (BMP):

- A copy of the facility's storm water pollution prevention plan (SWP3) was not available at the facility. A copy of the facility's SWP3 was received by Ohio EPA on January 6, 2012. A copy of the facility's SWP3 must be retained at the facility and be immediately available to Ohio EPA;
- An oil/water separator was installed in 2011. Ohio EPA records do not indicate that a permit-to-install (PTI) application was received and approved. The PTI application, including as-built plans, must be submitted to Ohio EPA that includes the following forms, which are available from the following website:
  1. Form A;
  2. Form B-5; and
  3. Appropriate PTI review fee.

<http://www.epa.ohio.gov/dsw/pti/PTIForms.aspx>

- Secondary containment was not available around the used oil tote storage area;
- 55-gallon drums were not properly capped and were stored exposed to precipitation events;
- Transmission fluid was present on the ground adjacent to the vehicle processing area; and
- Please submit copies of the outfall monitoring that was performed at the facility in 2010 and 2011 to Ohio EPA for review.

Please be aware that Ohio EPA has issued Industrial Storm Water General Permit OHR000005. You confirmed that you had received Ohio EPA's notification to submit a notice of intent for obtaining coverage under Ohio EPA's Industrial Storm Water General Permit OHR000005. The facility's SWP3 may require modification in order to comply with the requirements established within Industrial Storm Water General Permit OHR000005.

**Corrective Actions**

Appropriate best management practices (BMP) must be implemented to address the above deficiencies. A written report must be submitted to Ohio EPA within fourteen (14) days of receiving this notification that details how the deficiencies have been or will be addressed. The written report must also include dates detailing when each corrective action (i.e. BMP) was or will be implemented.

Should you have any questions regarding this matter, please contact me at your earliest convenience at (330) 963-1118 or via e-mail [chris.moody@epa.ohio.gov](mailto:chris.moody@epa.ohio.gov).

Sincerely,



Chris Moody  
Environmental Specialist II  
Division of Surface Water

CM/cs

cc: Lance Grimes, Metalico Youngstown, Inc.  
Glenda Brooks, Metalico Youngstown, Inc.  
Ben Sundelin, Metalico Youngstown, Inc.