



**Environmental
Protection Agency**

John R. Kasich, Governor

Mary Taylor, Lt. Governor

Scott J. Nally, Director

March 29, 2012

RE: HINCKLEY PLAZA
1309 RIDGE ROAD
PERMIT NO. 3PR00533*AD
MEDINA COUNTY
HINCKLEY TOWNSHIP

Mr. Ross Calabro
15151 York Road
North Royalton, Ohio 44133

CERTIFIED MAIL

Dear Mr. Calabro:

On March 2, 2012, an inspection of the above referenced facility's wastewater treatment system was conducted. No one was present to represent the facility. The purpose of the inspection was to evaluate the operation and maintenance of the treatment system along with the facility's compliance status with respect to the terms and conditions of the above referenced National Pollutant Discharge Elimination System (NPDES) permit.

During the inspection, the following items were noted:


1. The plant design of the wastewater treatment system is 1,500 gallons per day.
2. In accordance with Ohio Administrative Code (OAC) 3745-7-04, the sewage treatment facility is classified as a Class A facility. The classification requires that the operator of record be physically present at the treatment works two days per week for a minimum of one hour per week.
3. Per Part II of the facility's permit, the permittee shall designate one or more operator of record to oversee the technical operation of the treatment works in accordance with paragraph (A)(2) of rule 3745-7-02 of the Ohio Administrative Code. This office has no record of receiving the operator of record form. The operator of record form can be found at the following link: <http://www.epa.ohio.gov/dsw/opcert/opcert.aspx>.
4. Ohio operator certification rules require that a field log book be maintained at the treatment plant. The log book should document the time the operator is present at the treatment works along with maintenance duties being performed at the treatment plant.
5. The blowers were running and the plant was receiving good aeration.
6. The contents of the aeration tank were light to medium brown in color and a minimal amount of white foam was present.
7. The sludge return line was functioning properly and returning clear water. The sludge return line should be returning medium brown water. The side walls of the settling tank may need to be scraped down.
8. The skimmer level was properly adjusted.
9. The skimmer return line was functioning properly and returning clear water.
10. White foam was present behind the baffle in the settling tank.
11. The weirs and the trough in the settling tank were free of solids deposition.

Ohio

Environmental Protection Agency

Northeast District Office
2110 East Aurora Road
Twinsburg, OH 44087-1924

CERTIFIED MAIL



7011 0470 0002 3496 1863



RECEIVED

APR 10 2012

OHIO EPA NEDO

RS ↑

Mr. Ross Calabro
15151 York Road
North Royalton, Ohio 44133

LP
3/30 md

44133\$4821 0008



PS Form 3811, February 2004 Domestic Return Receipt 125507-02-11-1240

2. Article Number (Transfer from service label) 7011 0470 0002 3496 1863 Date 3/29/12

3. Service Type

Certified Mail

Express Mail

Registered

Return Receipt for Merchandise

Insured Mail

4. Restricted Delivery? (Extra Fee)

Yes

Mr. Ross Calabro
15151 York Road
North Royalton, Ohio 44133

D. Is delivery address different from item 1? Yes No

If YES, enter delivery address below:

A. Signature Agent Addressee

B. Received by (Printed Name) Date of Delivery

1. Article Addressed to:

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

SENDER: COMPLETE THIS SECTION COMPLETE THIS SECTION ON DELIVERY

HO