



**Environmental
Protection Agency**

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

May 10, 2012

Douglas Downs
Shencon Construction
PO Box 2475
Sandusky, Oh 44871

**Re: Construction Storm Water Inspection at OHIO BUSINESS COLLEGE / Franklin
County, Permit Number: 4GC03663*AG**

Dear Mr. Downs

This letter is written regarding a storm water inspection I conducted at Ohio Business College off Trueman Blvd. in Hilliard, Ohio on April 18, 2012. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. The following items were noted:

Sediment and Erosion Control:

- The centralized sediment basin was repaired per my last inspection report. The short circuit of the pond was eliminated
- The majority of the barren areas was seeded and mulch. There remains disturbed soils on the southern end of the site that must be seeded and mulched
- All perimeter controls must be maintained via your required self-inspection reports every seven days or within 24 hour of a rain event equal to or greater than 0.5 inches. A log of all inspection must be maintained.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response to the action items addressed in this letter.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Ohio Business College 4-18-2012