



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

March 12, 2012

Jeremiah Johnson
Beaver Excavating Company
2000 Beaver Place Avenue
Canton, OH 44706

Re: **Construction Storm Water Inspection at City of Columbus Upland Reservoir
Site #2 / Delaware County
Permit Number: 4GC03524 *AG**

Dear Mr. Johnson:

This letter is written regarding a storm water inspection/meeting at City of Columbus Upland Reservoir – Site #2 located at 10065 Taway Road Radnor, Ohio on March 16, 2012. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, our staff noted the following in association with construction activities at this site:

Sediment and Erosion Control:

- Please continue to implement positive drainage to sediment pond number one to minimize sediment discharges from the site.
- Continue with the stabilization efforts for all eligible areas which are barren and idle in excess of 21 days. All outlying slopes are a priority.
- During the inspection/meeting you indicated significant portions of the interior are barren but contained with minimal to no potential of discharge. I will be evaluating these areas within the next week to determine eligibility for temporary cover.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at 614-728-3844 or email at harry.kallipolitis@epa.state.oh.us.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

c: Jeff Bohne, Water Quality Supervisor, DSW / CDO

HK/nsm Upland Reservoir 7-14

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov



Figure 1: Sediment Pond #1 Outfall to Ottawa Creek



Figure 2: Sediment Pond #2 Outfall to Ottawa Creek



Figure 3: Outfall to Ottawa Creek Retention Pond From Pumping Activity on the South Side of Site