



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 26, 2012

Brian Grannan, Environmental Coordinator
Industrial Container Services
1385 Blatt Boulevard
Gahanna, OH 43230

Re: Construction Storm Water Inspection

Dear Mr. Grannan:

This letter is written in follow-up to a construction storm water inspection I conducted on June 20, 2012 of your recent land disturbing activities located at 1385 Blatt Boulevard in Gahanna, Ohio. Alicia Rector, Brittany Turner, Kathryne Rumora, and Elizabeth Pleta with Ohio EPA were present during this inspection. The site is specifically located at coordinates N39.99307, W82.83041, directly adjacent to Utzinger Ditch. Based on our evaluation, the following items were noted:

Sediment and Erosion Controls:

- I noted several areas where the silt fence was failing or not appropriately entrenched (See Attached Photos Figures 1 & 2). To ensure a properly functioning condition, all silt fence must be trenched into the ground a minimum of four to six inches. Stockpiling of dirt on the bottom of the fence is unacceptable. Please ensure all silt fence is maintained and properly entrenched. In addition, I noted a small area where the silt fence was not present.
- Additional non-erodible material is required for the temporary stream crossing of Utzinger Ditch. In addition, I strongly encourage contact with the Army Corps of Engineers at 304-399-5210 to ensure proper permitting.
- All areas should be properly graded to ensure the establishment of proper vegetative cover.

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response to this letter within seven days of receipt.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Industrial container 6-20-2012

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov



Figure 1. Case 1: Preoperative and Intraoperative



Figure 2. Case 2: Preoperative and Intraoperative