



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

June 29, 2012

Krisopher Nitz
Cabelas Retail Inc.
One Cabela Drive
Sidney, NE 69160

**Re: Construction Storm Water Inspection at Cabelas- Delaware, County
Permit# 4GC03809*AG**

Dear Mr. Nitz:

This letter is written regarding the storm water inspection conducted by Brittany Turner, Alicia Rector, Elizabeth Pleta, and Abigail Tamkin of the Ohio EPA at the northeast corner of Gemini Place and Lyra Drive on June 25, 2012. The Agency understands these construction activities are currently covered under Ohio EPA's General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

Sediment and Erosion Controls:

- The silt fence on the north, south, and west sides appear to require maintenance at this time. (See Figure 1)
- The silt fence on the southwest side of the site should be extended in order to ensure a proper functioning condition.
- The concrete washout containment area near the site entrance requires maintenance. (See Figure 2)
- Concrete activities were noted on the north edge of the site. A washout containment area must be established to ensure compliance with the general permit. (See Figure 3)

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Cabelas Delaware County 6-25-2012

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov




Figure 1 Silt fence needs maintained




Figure 2 Maintain concrete washout pit



Figure 3 Establish concrete washout pit