



Environmental  
Protection Agency

John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Nally, Director

July 05, 2012

Cole Ellis  
Cardinal Self Storage Worthington LLC  
1301 Dublin Road Suite 200  
Columbus, OH 43214

**RE: Storm Water Inspection at Cardinal Self Storage Worthington LLC**  
**Permit Number: 4GC03732\*AG**

Dear Mr. Ellis:

This letter is written in follow up to a construction storm water inspection by Alicia Rector and Elizabeth Pleta of the Ohio EPA, at Cardinal Self Storage Worthington LLC located at 7535 Alta View Boulevard on July 03, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

**Sediment and Erosion Controls**

- The silt fence on the northern portion of the site has failed and will require maintenance at this time.
- Inlet protections are required provided the storm sewer system is not routed to an approved centralized sediment basin (See Photo Figure 1).
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days. This specifically applies to the disturbed areas noted in Figure 2.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Cardinal Self Storage 7-3-2012



Figure 1: Void of Dandy Bag




Figure 2: Lacking Protection from Erosion