



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

July 17, 2012

Steve Kirkland
Aleris International Inc.
25825 Science Park Drive Suite 400
Beachwood, OH 44122

**Re: Notice of Violation Storm Water Inspection at Aleris Rolled Products Inc.,
Pickaway County Permit Number: 4GC03718*AG**

Dear Mr. Kirkland:

This letter is written in follow up to a construction storm water inspection by Elizabeth Pleta and Alicia Rector of the Ohio EPA, at Aleris Rolled Products Inc. located at 1 Reynolds Road on July 6, 2012. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:


- The use of straw bales within the ditch line fails to meet the minimum criteria of the permit (See Figure 1). The ditch line noted in must be graded and protected from erosion within seven (7) days. This criteria applies to all effected and eroding stream segments adjacent to the property.
- Perimeter controls must be established for all barren areas exhibiting sheet flow into the stream/ ditch surrounding the property (See Figure 2).
- Out staff noted one perimeter control on the northeast corner which was in disrepair (See Figure 3). This must be repaired within seven (7) days in order to meet the conditions of the General Permit.
- The concrete washout containment area requires maintenance (See Figure 4).
- Please ensure containment of concrete batching meets compliance with the general permit (See Figure 5).

Steve Kirkland
Aleris International Inc.
Page -2-

- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,



FOR
Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office



Figure 1 Ungraded ditch line located on northwest side of sire lacking proper perimeter controls.



Figure 2 Barren area lacking perimeter controls.



Figure 3 Silt fence functioning improperly.



Figure 4 Concrete washout requiring maintenance.



Figure 5 Containment of concrete batching must be ensured