



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 2, 2012

Kenneth L. Koppes
Edinburgh Cove LTD
1038 Edinburgh Cove
London, OH 43140

Re: Edinburgh Cove II & III / Madison County

Dear Mr. Koppes:

This letter is written in follow-up to a construction storm water inspection that I conducted on July 25, 2012, at Edinburgh Cove II & III located at the end of Wesley Drive in London, Ohio. The purpose of the inspection was to ensure continued compliance with the General Storm Water Permit Associated with Construction Activities. The site had no active construction. During the inspection, I noted the following:

Sediment and Erosion Controls:

- There was no active construction. Most of the site was stabilized except for a few small areas that may need to be re-seeded in the fall. No erosion was leaving the site.
- It was noted that there was recent stockpiling of dirt. If the stockpile becomes too large, it may need to be stabilized and erosion controls placed around the perimeter. It currently does not appear to be a concern.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3851.

Sincerely,

Gregory L. Sanders
Environmental Specialist
Division of Surface Water
Central District Office

ec: Gregory L. Sanders, DSW/CDO

GS/nsm Edinburgh Cove II & III, July 25, 2012

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov