



**Environmental
Protection Agency**

1600 East 12th Avenue, Columbus, OH 43260
Governor
Lt. Governor
Director

September 6, 2012

Kristin Poldemann
Ohio State University
400 Central Classroom Bldg
2009 Millikin Road
Columbus, Ohio 43210

Re: Storm Water Inspection Permit Number 4GC03368*AG

Dear Ms. Poldemann:

This letter is written regarding the storm water inspection I at the Ohio State University South Oval on August 28th, 2012. The Agency understands these construction activities are currently covered under the General Storm Water Permit Associated with Construction Activities. Based on the site inspection and the General Storm Water Permit, the following items must be addressed:

Sediment and Erosion Controls:

- During the inspection I noted a majority of the site is currently draining to a centralized basin located on the western perimeter of the site. Please continue to ensure positive drainage to this basin intended for sediment control.

Dewatering Activities:

- During the inspection I noted what appeared to be a 3-inch pump established for dewatering the centralized pit onto the south oval commons. Please be aware that all dewatering activity must be conducted in such a manner not to result in turbid discharges to waters of the state, namely, the Olentangy River

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm OSU South Oval 8-28-2012

Central District Office
50 West Town Street, Suite 700
P.O. Box 1049
Columbus, OH 43216-1049

614 | 728 3778
614 | 728 3898 (fax)
www.epa.ohio.gov