



John R. Kasich, Governor  
Mary Taylor, Lt. Governor  
Scott J. Mallory, Director

January 3, 2013

Robert Johnson  
Liqui-Box Corporation  
6950 Worthington-Galena Road  
Worthington, Ohio 43085

**Re: Industrial Storm Water Inspection at Liqui-Box Corporation  
Permit Number: 4GR000129\*AG**

Dear Mr. Johnson:

This letter is written regarding my storm water inspection conducted at Liqui-Box Corporation located on Worthington Galena Road in Franklin County on December 31, 2012. I understand this facility was covered under the General Storm Water Permit Associated with Industrial Activities. Your facility permit number is 4GR00129\*AG. The following items were noted during the inspection

**Storm Water Permit:**

- The General Permit for this facility has expired. The facility must seek re-authorization under the Multi Sector General Storm Water Permit. The permit, application and guidance material can be found at the following address  
[http://www.epa.ohio.gov/dsw/permits/GP\\_IndustrialStormWater.aspx](http://www.epa.ohio.gov/dsw/permits/GP_IndustrialStormWater.aspx).  
Failing to renew coverage is a direction violation of 40CFR 122.26 and OAC 3745-39
- Please submit your application for renewal within seven days from receipt of this letter.

**Storm Water Pollution Prevention Plan (SWPPP):**

- The SWPPP must be updated within 180 days to reflect the new conditions of the General Permit. Again, please refer to your specific sector for the additional conditions in the link provided above for reference.

**Monitoring:**

- The specific sector for your facility requires monitoring. A visual evaluation of the storm water discharge is required on a quarterly basis. The SWPPP must identify the location of the outfall for this site. Additional sampling may be required based on the sector specific requirements. Please see link above for reference.

**Site Observations:**

- During the inspection, I noted four large tanks on the north end of the property. However, I was unable to closely evaluate any proposed Best Management Practice (BMP) associated with the storage tanks as no personnel were available at the time of my inspection. The facility appeared closed for the Holidays.
- Secondary containment is expected for all storage tanks containing materials which could pose a threat to storm water quality.
- Inspection protocols should be in place for this site to assess potential threats to storm water. Please contact me upon receipt of this letter to further discuss my inspection.

If you have any questions regarding this letter or my inspection, please contact me at 614-728-3844 or via email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us).

Sincerely,



Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office