



Environmental
Protection Agency

John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

August 27, 2012

David Wespiser
Hotel Development Services LLV
125 West Spring Street
Oxford, OH 45058

**Re: Storm Water Inspection at Marriott Courtyard- New Albany, Franklin County
Permit Number: 4GC03490*AG**

Dear Mr. Wespiser:

This letter is written in follow-up to a construction storm water inspection by Elizabeth Pleta and Alicia Rector of the Ohio EPA, at Marriott Courtyard- New Albany located at North side of Forest Drive 1015' east of Smith's Mill Road, West side of Forest Drive 340' south of US Route 62 on August 7, 2012. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:


Sediment and Erosion Controls

- The silt fence located in the southeast portion of the site requires maintenance (See Figure 1).
- It was noted that the silt fence located in northeast corner of the site needs to be extended (See Figure 2).
- It appears that there is an intended bypass of the sediment control on the inlet located in the northeast end of the site. Please reset the inlet protection immediately (See Figure 3).
- Please ensure maintenance of all inlet protection and dandy bags.
- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

David Wespiser
Hotel Development Services LLV
Page -2-

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

A handwritten signature in black ink, appearing to read "Harry Kallipolitis", written over a faint, illegible printed name.

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Marriott Courtyard New Albany 8-13-2012




Figure 1 Silt fence not entrenched and requires maintenance.



Figure 2 Extension of silt fence required along Forest Drive.




Figure 3 Bypass off inlet protection.