



180 years and moving forward

John R. Kasich, Governor
Janez Pichler, Lt. Governor
Scott J. Staley, Director

March 6, 2013

Hanlin Rainaldi Construction Corporation
6610 Singletree Drive
Columbus, Ohio 43229

Re: Sam's Club #6326-04, Reynoldsburg, Ohio, Permit Number 4GC03046*AG

Dear Sir or Madame:

This letter is written in follow-up to my site observations of the post construction water quality treatment measures noted at the Sam's Club in Reynoldsburg, Ohio on December 31, 2012, with follow-up on February 25, 2013.

I remain unclear if the water quality basin located on the north end of the property is functioning as required. I noted the recent installations of a forebay and micro pool. However it was my understanding the discharge structure would be modified to address a water quality release. The basin should be designed to discharge a water quality volume associated with a 0.75 inch rain event over a 48 hour period. The current outlet structure does not appear to accommodate this requirement.

Please ensure the forebays and micro pools are cleaned out as found necessary as the two act as a repository for accumulated sediments.

In the event accumulated water in the basin remains in excess of 48 hours or is discharge prior to a 48 hour period following each significant rain event, it is evident there is a malfunction.

If you have any questions regarding this letter or my inspection, please contact me at 614-728-3844 or via email at harry.kallipolitis@epa.state.oh.us to discuss this issue in detail.

Sincerely,

For HK
Harry Kallipolitis
Environmental Specialist
Division of Surface Water
Central District Office

HK/nsm Sams Club 2-25-2013