



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

April 11, 2013

Matt Foor
Performance Training School
7791 Taylor Road
Pataskala, OH 43068

**Re: Construction Storm Water Inspection at Performance Training School
7791 Taylor Road, Pataskala, Ohio
Permit Number 4GC003631*AG**

Dear Mr. Foor:

This letter is written in follow-up to a construction storm water inspection I conducted at Performance Training School located at 7791 Taylor Road, in Pataskala, Ohio on April 4, 2013 in follow up to my initial inspection on November 15, 2011. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit Associated with Construction Activities. During the inspection, I noted the following issues associated with construction activities at this site:

Sediment Controls:

- It is imperative this site implements a sediment control structure designed specifically to accommodate a de-watering volume as required by the general permit. Based on the nature of the ongoing earth disturbing activity, an effective sediment basin is paramount. I recommend the use of a skimmer to increase effectiveness. This issue was brought to your attention during my last onsite meeting/inspection..

If you have any questions regarding this letter or the inspection, please do not hesitate to call me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. In addition, please provide a written response (**email preferred**) to the action items addressed above within ten days from receipt of this letter. A follow-up inspection will be conducted to ensure the minimum conditions of the General Permit have been met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HK/nsm Performance Training School April 4, 2013