



John W. Kasich, Governor  
Frank Lauder, Lt. Governor  
Scott J. Nandy, Director

August 5, 2013

Mark Edwards  
Equity  
445 Hutchinson Avenue, Suite 800  
Columbus, Ohio 43235

**Re: Storm Water Inspection at Timberline Office Campus/ Franklin County.  
Permit #: 4GC04170\*AG**

Dear Mr. Edwards,

This letter is written in follow up to a construction storm water inspection by Jerome Hoke and Paul Hafner, of the Ohio EPA, at Timberline Office Campus located at 4595, 4605, and 4611 Trueman Boulevard on July 16, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

### **Sediment and Erosion Controls**

- Silt fence is absent on the eastern portion of the site and will require installation within three (3) days from receipt of this letter (See Figure 1).
- There appear to be two sediment basins on the southeast corner of the site (See Figure 2). The General Permit requires modifications to address sediment control. Please ensure a riser/skimmer is set to an elevation to accommodate the required storage of 67 cubic yards per acre of drainage

### **21 Day Rule**

- Be aware the General Permit states that all barren areas which remain idle in excess of 21 days must be protected from erosion within seven days of the last earth disturbing activities. In addition, erosion protection must be implemented for all areas of final grade within seven (7) days.

Mark Edwards  
Equity  
Page 2


If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at [harry.kallipolitis@epa.state.oh.us](mailto:harry.kallipolitis@epa.state.oh.us). A follow-up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,




Harry Kallipolitis  
Storm Water Coordinator  
Division of Surface Water  
Central District Office

HK/nsm Timberline Office Campus 7-16-13



Timberline Office Camp  
Scioto River Watershed  
Photo by Jerome [unreadable]  
[unreadable]

**Figure 1: Silt fencing absent on eastern side of site.**



**Figure 2: Possible sediment basins require a riser and/or skimmer**