



October 2, 2013

Mark Waller
South-Western City Schools
3805 Marlene Drive
Grove City, OH 43123

RE: Construction Storm Water Inspection at Harmon Elementary School / Franklin County. Permit Number: 4GC04034*AG

Dear Mr. Waller,

This letter is written regarding a storm water inspection conducted by Jerome Hoke and Elizabeth Pleta of the Ohio EPA at Harmon Elementary School located on the southwest corner of the Frank Road and Gantz Road intersection on September 23, 2013. The purpose of the inspection was to evaluate compliance with the General Storm Water Permit associated with Construction Activities. During the inspection, our staff noted the following issues associated with construction activities at this site:

Sediment and Erosion Control:

- During the inspection, we noted the sediment pond on the west side of the site still lacked a properly modified outlet structure (See Figure 1). The site superintendent assured us that a skimmer would be installed within the week. Please ensure the skimmer's installation occurs before our next monthly site inspection. Further compliance efforts may be taken on behalf of the Ohio EPA if installation is not complete.
- Please be aware measures are expected to ensure all barren areas are properly protected in preparation for the upcoming winter months. In the event earth disturbing activities extend beyond an effective growing season, alternate erosion protection is expected. This would include but not limited to a crimped straw mulch cover. Please submit to my attention the temporary seeding/protection schedule to ensure the erosion protection requirements are not violated.

If you have any question regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844 or email at harry.kallipolitis@epa.state.oh.us. A follow up inspection will be conducted to ensure the conditions of the General Permit are met.

Sincerely,

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Ohio EPA

c: Jeff Bohne, Water Quality Supervisor, DSW/CDO
Ryan Felumlee, Superintendent, Robertson

HK/slw Harmon Elementary School 9-23-13

Harmon Elementary School
Scioto River Watershed
Photo By: Elizabeth Pieta
9/23/13



Figure 1: Sediment basin requires installation of skimmer.