



October 7, 2013

Tucker Bohm
The Daimler Group
1533 Lake Shore Drive
Columbus, Ohio 43204

Re: Storm Water Inspection at Perimeter Retail Development/ Franklin County, Permit Number: 4GC04080*AG

Dear Mr. Bohm:

This letter is written in follow up to a construction storm water inspection by Elizabeth Pleta and Jerome Hoke, of the Ohio EPA, at Perimeter Retail Development located at 6566 Perimeter Drive on September 17, 2013. The purpose of the inspection was to evaluate compliance with Ohio EPA's General Storm Water Permit Associated with Construction Activities. During the inspection, we noted the following:

Sediment and Erosion Controls:

- It appears the perimeter silt fence on the south side of the site has become overburdened and will require maintenance within three (3) days of receiving this letter (See Figure 1).
- The inlets on this site lack proper protection (See Figure 2). Inlet protections are required for this site and must be installed within three (3) days of receiving this letter.

If you have any questions regarding this letter or the inspection, please do not hesitate to contact me at our Central District Office at (614) 728-3844. Follow-up inspections will be conducted to ensure the conditions of the General Permit are continuing to be met.

Sincerely,

A handwritten signature in blue ink that reads "Harry Kallipolitis". Below the signature, the initials "FAR H.K." are written in blue ink.

Harry Kallipolitis
Storm Water Coordinator
Division of Surface Water
Central District Office

HRK/slw

Perimeter Retail Development.9-17-13



Figure 1 Overburdened silt fence on south side of site.




Figure 2 Exposed inlet requires installation of dandy bag for protection.