

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

George Hadchiti  
Hadchiti Inc. / Sunora  
6000 Rockside Rd.  
Independence, OH 44131

2. Article Number  
(Transfer from service label)

7009 3410 0002 1934 1202

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature

X

Agent

Addressee

B. Received by (Printed Name)

C. Date of Delivery

D. Is delivery address different from item 1?  Yes

If YES, enter delivery address below:  No

Hand delivered  
12/3/10

3. Service Type

Certified Mail

Express Mail

Registered

Return Receipt for Merchandise

Insured Mail

C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes



City of Cleveland  
Frank G. Jackson, Mayor

Department of Public Health  
Division of Air Quality  
75 Erieview Plaza, Suite 200  
Cleveland, Ohio 44114-1839  
216/664-2297 • Fax: 216/420-8047  
www.clevelandhealth.org

**SERVING OHIO EPA AS AGENCY 13  
FOR CUYAHOGA COUNTY**

**CERTIFIED MAIL 7009 3410 0002 1934 1202  
RETURN RECEIPT REQUESTED**

November 3, 2010

George Hadchiti  
Hadchiti, Inc.  
6000 Rockside Road  
Independence, OH 44131

NON-HPV

**FACILITY ID: 13-18-27-6221**

**NOTICE OF VIOLATION: Failing Annual Stage II testing**

Dear Mr. Hadchiti:

On November 2, 2010, the Cleveland Division of Air Quality (CDAQ) inspected Sunoco (Hadchiti, Inc.) located at 6000 Rockside Road in Independence. This letter serves as notification that you are operating sources in violation of the following applicable air statutes, air regulations, or air permit conditions.

Hadchiti, Inc. failed an Air-to-Liquid (A/L) ratio test on dispenser #8 on November 2, 2010. Each failure to successfully pass the testing requirements specified in Ohio Administrative Code (OAC) Rule 3745-21-09(DDD)(2) while causing, allowing or permitting the transfer of gasoline from a stationary storage tank into a motor vehicle is a violation of Ohio Revised Code (ORC) Chapter 3704.05(G) and OAC Rule 3745-21-09(DDD)(1)(c).

Unless you undertake some type of corrective action with respect to the above noted violations, you will remain in non-compliance. CDAQ requests that Hadchiti, Inc. make the necessary repairs to dispenser #8, conduct a re-test of the Air-to-Liquid Ratio test and then submit test results within thirty (30) days of receipt of this letter to the following enforcement representative:

Megan Murphy  
Cleveland Division of Air Quality  
75 Erieview Plaza 2<sup>nd</sup> Floor  
Cleveland, Ohio 44114-1839

If there is insufficient time to correct the alleged violations within this timeframe, a written response which includes a timeline for correcting the alleged violations must be received within thirty (30) days of receipt of this letter.



Violations of Ohio air pollution laws and /or permit terms and conditions are subject to the penalties stipulated in Ohio Revised Code Section 3704.99(A), which allows fines of not more than twenty-five thousand dollars or imprisonment for not more than one year, or both, for each violation.

CDAQ issues this letter with Ohio EPA's concurrence. The failure to mention any specific violation does not excuse any violations of local, state and federal laws or regulations regarding air pollution control. Violations of air pollution control laws may be pursued in local court or referred to Ohio EPA or U.S. EPA for further enforcement action. Should you have any questions, please call Megan Murphy at 216-664-4258. All correspondence with CDAQ must include the Ohio EPA facility identification number for Hadchiti, Inc.: 13-18-27-6221.

Sincerely,

*Linda Kimmy for G.B.*

George Baker  
Chief of Enforcement

GB/mm

cc: Michael J. Krzywicki, CDAQ  
John Paulian, Ohio EPA Central Office  
William MacDowell, U.S. EPA Region V  
Facility File and L:\Data\Facilities\1318276221\2010-11-2 NOV.doc