



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

June 17, 2008

RE: REPUBLIC ENGINEERED PRODUCTS  
DAPC FACILITY ID # 02 47 08 0229  
RETURNED TO COMPLIANCE:  
EMISSIONS UNIT P081 –  
BLOOM REHEAT FURNACE

Mr. Jay Lawniczak  
Environmental Manager  
Republic Engineered Products  
1807 E. 28<sup>th</sup> Street  
Lorain, OH 44055

Dear Mr. Lawniczak:

This letter is to acknowledge that Republic Engineered Products ("Republic") has brought the Bloom reheat furnace back into compliance with the NO<sub>x</sub> limit of 0.132 lb/MMBtu.

The Ohio EPA, Northeast District office, issued two notices of violation dated January 2, 2008 and March 12, 2008, for not complying with the aforementioned limit.

Republic had submitted a compliance plan dated January 21, 2008.

The Ohio EPA, Northeast District office, received and completed of review the NO<sub>x</sub> emissions testing report. The testing was conducted on April 8, 2008. The average emissions rate of NO<sub>x</sub>, based on three, one-hour test runs was 0.044 lb/MMBtu.

If you have any questions concerning this letter, please contact me at (330) 963-1187.

Sincerely,

Tony Becker  
Environmental Specialist  
Division of Air Pollution Control

TB:bo

cc: Lisa Holscher, U.S. EPA Region V

ec: Bob Princic, DAPC-NEDO  
Dennis Bush, DAPC-NEDO  
Tom Kalman, DAPC-CO