



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

February 9, 2007

RE: NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
BP #22380
Ohio EPA ID #0243111049

CERTIFIED MAIL

Ms. Becky Stackhouse
BP Products North America
P.O. Box 6038
Artesia, CA 90702

Dear Ms. Stackhouse:

The annual Stage II compliance test conducted at BP #22380 located at 7515 Auburn Road in Painesville, Ohio 44077, on January 26, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed dispenser #7 only
Static Leak Test	Passed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The vacuum pump on dispenser #7 had no vacuum.

Our inspector also noted that the hoses on dispensers #1, #2, and #7 need to be replaced.

Please schedule repairs and conduct a retest within 30 days of your receipt of this letter.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB/mt

cc: Bob Princic, Ohio EPA, DAPC, NEDO
Tom Kalman, Ohio EPA, DAPC, CO
Lisa Holscher, U.S. EPA, Region V
Station Manager