



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.  
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769  
www.epa.state.oh.us

Ted Strickland, Governor  
Lee Fisher, Lieutenant Governor  
Chris Korleski, Director

February 20, 2007

RE: NOTICE OF VIOLATION  
FAILED ANNUAL STAGE II COMPLIANCE TEST  
BP #86519/04981  
OHIO EPA ID #0243161063

CERTIFIED MAIL

Becky Stackhouse  
BP Products North America  
PO Box 6038  
Artesia, CA 90702

Dear Ms. Stackhouse:

The annual Stage II compliance test conducted at BP #86519/04981 located at 4015 Erie St. in Willoughby, Ohio on February 9, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Passed
Static Leak Test	<b>Failed</b>
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Please complete the necessary repairs and conduct a retest within three weeks of your receipt of this letter. We have noted that the Static Leak tests conducted in 2004 and 2005 also failed their initial tests.

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush  
Environmental Manager  
Division of Air Pollution Control

DB:bo

cc: Bob Prinic, DAPC, NEDO  
Tom Kalman, DAPC, CO  
Lisa Holscher, USEPA, Region V  
Station Manager