



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 487-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

December 31, 2007

RE: **NOTICE OF VIOLATION**
DENMAN TIRE CORPORATION
HIGH PRIORITY FACILITY
DAPC FACILITY ID 02-43-03-0583
EMISSIONS UNIT ID # B001

CERTIFIED MAIL

Mr. Tom Gay
Plant Supervisor
Denman Tire Corporation
400 Diehl South Rd.
Leavittsburg, OH 44430

Dear Mr. Gay:

A copy of the stack test report, which was conducted at 400 Diehl South Rd. in Leavittsburg, Ohio on October 18, 2007, was received by this office on November 27, 2007. After a review of the report, it has been determined, based on an average of three runs, that the Coal-Fired Springfield Boiler (B001) did not demonstrate compliance with the mass emission limit of 0.28 lb/MMMBtu for particulate matter. Specifically, the average emission rate was calculated to be 0.295 lb/MMBtu.

Denman Tire Corporation is required to make necessary repairs to bring this emissions unit into compliance. You are required to provide an acceptable compliance plan to this office within thirty (30) days of receipt of this notice, demonstrating how compliance will be accomplished. The plan should also include a date for a retest of the Coal-Fired Springfield Boiler. Following review of this compliance plan, this office will make recommendation, as to whether the proposed compliance plan will achieve the necessary result of regulatory compliance.

Please contact me at (330) 963-1273 if you have any further questions on this matter.

Sincerely,

Ed Perez
Environmental Specialist
Division of Air Pollution Control

EP/mt

cc: Dennis Bush, Ohio EPA, DAPC, NEDO
Dave Konrad, HzW Environmental Consultants
Lisa Holscher, U.S. EPA, Region 5

ec: Ed Fasko, Ohio EPA, DAPC, NEDO
Bob Princic, Ohio EPA, DAPC, NEDO
Tom Kalman, Ohio EPA, DAPC, CO