



State of Ohio Environmental Protection Agency

Northeast District Office

2110 East Aurora Rd.
Twinsburg, Ohio 44087

TELE: (330) 963-1200 FAX: (330) 467-0769
www.epa.state.oh.us

Ted Strickland, Governor
Lee Fisher, Lieutenant Governor
Chris Korleski, Director

December 17, 2007

RE: SECOND NOTICE OF VIOLATION
FAILED ANNUAL STAGE II COMPLIANCE TEST
BP #22384
OHIO EPA ID #0228000211

CERTIFIED MAIL

Becky Stackhouse
BP Products North America
PO Box 6038
Artesia, CA 90702

Dear Ms. Stackhouse:

The annual Stage II compliance RETEST conducted at BP #22358 located at 8501 Mayfield Rd. in Chesterland, Ohio 44026 on November 19, 2007, failed to demonstrate compliance for the following parameters:

<u>Parameter</u>	<u>Pass/Fail</u>
A/L Test	Failed dispenser #4 only
Static Leak Test	Failed
Dynamic Pressure Test	Not required this year
Ohio EPA Inspection	Passed

The static leak test failed due to a leaking ATG cap. This is the same problem that caused the first test this year on October 1, 2007, to fail. You should not schedule retests unless the problems are repaired. This is a waste of our time to witness tests were the repairs have not been made.

Please schedule repairs and conduct a retest within 30 days of your receipt of this letter. Please submit a copy of the maintenance records that document that the repairs have been completed and this site should be ready to pass a retest.

Failed test results constitute a violation of OAC Rule 3745-21-09 (DDD).

Violation of state air pollution control regulations are punishable by a civil penalty of \$25,000 per violation. Issuance of this notice does not excuse any violation of state law regarding air pollution.

Sincerely,

Dennis Bush
Environmental Manager
Division of Air Pollution Control

DB:bo

cc: Bob Princić, DAPC, NEDO
Tom Kalman, DAPC, CO
Lisa Holscher, USEPA, Region V
Station Manager